



Volkswagen Golf (UKL): 2CHY427

Vinnumber:	WVWZZZCD8PW503850	Versionname:	Golf VIII Variant Life 1.5TGi 130pk/cv 5p
First Registrationdate:	4/08/2022	Fiscalpower:	
Expertise Mileage:	50292	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Gas		
Maintenance	OK		
Maintenance	plus 4000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/91 H			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Ignition key, Missing, Replace			



Interior, Smell, Ozone treatment



Bumper F, Dent(s), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Replace



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Repair and paint (complete)





Outer sill R, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Kenteken	2CHY427
Merk Model	Volkswagen Golf VIII Variant Life 1.5TGi 130pk/cv 5p
Brandstofsoort	CNG
Datum deel1	8/4/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/15/25	39,231	klein materiaal	
10/15/25	39,231	ruitenwisserrubber achter	Vervangen
10/15/25	39,231	ruitenwisserrubber vooraan	Vervangen
10/15/25	39,231	ruitenwisservloeistof	Bijvullen/-laden
10/15/25	39,231	Tussentijds onderhoud (vast interval)	Uitvoeren
10/9/24	33,046	airco systeem reiniging	Uitvoeren
10/9/24	33,046	Inspectie met olie vervanging (vast interval)	Uitvoeren
10/9/24	33,046	klein materiaal	
10/9/24	33,046	koelwatervloeistof	Bijvullen/-laden
10/9/24	33,046	luchtfilter interieur	Vervangen
10/9/24	33,046	remvloeistof	Vervangen
10/9/24	33,046	ruitenwisservloeistof	Bijvullen/-laden
9/13/23	16,958	Inspectie met olie vervanging (vast interval)	Uitvoeren
9/13/23	16,958	klein materiaal	Uitvoeren
9/13/23	16,958	ruitenwisserrubber achter	Vervangen
9/13/23	16,958	ruitenwisserrubber vooraan	Vervangen
9/13/23	16,958	ruitenwisservloeistof	Bijvullen/-laden