



Polestar 2: L121RB

Vinnumber:	LPSVSEDEEML023517	Versionname:	Polestar 2 (outgoing) AWD 300kW/ 78kWh Pilot Plus
First Registrationdate:	23/07/2021	Fiscalpower:	
Expertise Mileage:	131898	Power Kw:	300
Bodytype:		Body colour:	Void
Gearbox:	Automatic	Paint type:	Opaque
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	1094
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Panoramic roof
GPS		Rear parking sensors
Autom climate control		Hook
Radio multimedia		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / Y / Aluminium	6,3 mm	Continental	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	6,5 mm	Continental	Summer
Rear	Left	245 / 45 / 19 / 102 / Y / Aluminium	5,5 mm	Continental	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	6,2 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Interior, Stain, Cleaning



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)





Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Rear window, Scratch(es), Replace



Kenteken	L121RB
Merk Model	Polestar Polestar 2 (outgoing) AWD 300kW/ 78kWh Pilot Plus
Brandstofsoort	Elektrisch
Datum deel1	23-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
19-12-25	116.478	Onderhoudsbeurt
19-12-25	116.478	Ruitenwischerblad(en) voorzijde
23-09-25	111.928	High Voltage kabel ECU
05-06-25	103.532	APK
05-06-25	103.532	Boordcomputer
16-10-24	88.392	Sleutel/Kaart
24-09-24	87.512	Onderhoudsbeurt
03-01-24	68.781	Vervanging band
14-09-23	59.118	Onderhoudsbeurt
14-09-23	59.118	Remvloeistof
14-09-23	59.118	Ruitenwischerblad(en) voorzijde