Volkswagen

VOLKSWAGEN TAIGO (CS1)(08.2021->) LIFE MOTEUR 1,0 LITRE(S) - 81 KW TSI 5 PORTES

VIN: WVGZZZCSZPY031851



Description

Registration number 2CXS824	**Registration date** 06/01/2023	**Odometer** 87841 km
Color Gris Fumée Métallisé	**Year** 2021	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
CO2 139	**Engine displacement** 999	**Gearbox type** Automatic
Engine type Combustion	**Fuel Type** Petrol	**Number of gears** 7
Drivetrain Front Wheel Drive (FWD)	**Max power** 81 KW	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Vehicle Equipments

Standard

- driver assistance system: lane assist
- center armrest front sliding, with storage compartment
- display for coolant level (wiper system)
- Parkpilot system front and rear
- airbag driver side/passenger side, passenger-side airbag deactivatable
- sidebag front with Center airbag, head airbag unit front and rear
- alarm system for seat belts front and rear
- automatic headlight control (ALS) with Leaving Home / Coming Home light function
- immobilizer (electronic)
- head rests rear (3-fold)
- head rests front safety-optimised
- roof rails
- first-aid kit and warning triangle
- body: 5-door
- 3-point seatbelt rear center
- seat belts front with seat belt tensioner and end fitting tightener, height-adjustable
- radio-remote key (2) hinged
- steering column (steering wheel) mech. height/longitudinal adjustment
- Electronic Stability Control (ESP) brake assistant, ASR/ABS, EDS, trailer stabilisation, MSR
- antilock braking system (ABS)
- Digital cockpit (instrument display digital)
- power steering
- rear seat backrest split
- wheelbase 2554 mm
- Longlife-Service
- equipment Comfortline / Life / Business
- interior equipment decorative trim inserts Micro metallic
- rear window wiper
- rear lights LED
- rear fog light
- Interior filter: active combination filter
- roof liner cloth, gray
- Bluetooth interface for mobile phone
- Light-alloy rims
- tire repair kit
- map light front
- shift/selector lever leather
- window lifter electric front + rear
- Type of drive: front-wheel drive
- chrome package (1)
- non-smoking package
- windshield laminated glass tinted
- bumper Life
- sun visors with mirror (illuminated)
- instrument panel in synthetic leather Artico
- cargo space floor height-adjustable
- tire 205/60 R16 ..H
- hand brake lever leather
- headlight LED
- radio reception digital (DAB+)
- headlight leveling control
- exterior mirror with perimeter light and projection feature
- exterior mirror vehicle colour
- exterior mirror electrically adjustable, heated + folding with mirror down-tilt feature right
- seat covers/upholstery: cloth Life
- seats front height-adjustable
- standard seats front
- Isofix mounts for child seat at passenger seat and rear seat (incl. i-Size child seats)
- floor mats textile
- driver assistance system: safety system SYNC with automatic emergency call
- driver assistance system: hill-start assist (Hill-Holder)
- driver assistance system: alertness assistant
- driver assistance system: pedestrian detection
- driver assistance system: periphery observation system (Front assist) with City emergency braking function
- start/stop system with Rekuperation
- sliding console front center
- tire puncture indicator
- central locking system
- central locking system with remote control
- steering wheel (leather) with multiple function and shift function

Optional

- generator 140 A
- antenna diversity
- transmission 7-speed - dual-clutch transmission S-tronic
- reversing camera
- front camera (multi-functional camera windshield)
- air conditioning Climatronic 2-zone
- Disques de frein AR (230 mm x 9 mm)
- dual tailpipe exhaust system chrome
- windshield wiper with rain sensor
- navigation function Discover Media incl. Streaming & Internet (colour touchscreen)
- driver assistance system: traffic sign detection
- audio system Ready 2 Discover (incl. Streaming & Internet, Touchscreen, Bluetooth)
- App-Connect incl. App-Connect Wireless (Apple CarPlay, Android Auto)
- speaker(s) (6)
- multi-media interface 2 x USB (type C) front and 2 x USB charging port (type C) center console rear
- Moteur 1,0 litre(s) - 81 kW TSI Catalyseur (DLAA)
- low emissions according to emission standard Euro 6d
- jack
- Equipment package: Light and Vision
- interior mirror with automatic dimming
- Driver assistance package: Travel Assist and lane assist
- Lounge package (incl. seat covers/upholstery: cloth/leather)
- metallic paintwork
- mobile online services preparation We Connect and We Connect Plus
- stabilizer front
- driver assistance system: automatic distance control (ACC incl. Stop&Go function)
- glazing rear darkened (75%)

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	10/08/2026	11/08/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Interior complete / -	Stained	Cleaning
			
002	Spare Key / -	Missing	Replace
			
003	Wing / Back Left	Dent	Acceptable
			

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [ ] Toolkit
- [ ] Load cover
- [x] Conformity certificate
- [ ] Locking wheel nut
- [x] Remote key
- [ ] Towing hook
- [ ] Cargo net
- [ ] Security Kit
- [ ] Satellite navigation
- [x] Document holder
- [ ] Charging cable bag
- [ ] First aid kit
- [ ] Slow charging cable (Type 2, Mode 2)
- [ ] Service book
- [x] Registration certificate
- [ ] Card key
- [x] Compressor tyre repair kit
- [ ] Hook /Hicth ball
- [ ] Safety vest
- [ ] Jack handle crank
- [ ] In-car tools
- [ ] Refill tyre repair kit
- [ ] Remote control
- [ ] Quick charging cable (Type 2, Mode 3)
- [ ] Warranty booklet
- [x] Registration certificate owner
- [ ] Locking wheel nuts key
- [ ] Jack
- [ ] Spare Key
- [ ] Tyre repair kit complete
- [x] User manual
- [x] Rear parcel shelf
- [ ] Spare wheel tyre
- [ ] Triangle

Main set of tyres

Front Left	GOODYEAR	205 / 60 / 16 / Summer	6 mm
Front Right	GOODYEAR	205 / 60 / 16 / Summer	6 mm
Back Left	GOODYEAR	205 / 60 / 16 / Summer	6 mm
Back Right	GOODYEAR	205 / 60 / 16 / Summer	6 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right



Odometer



Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Interior complete / - / Stained



Spare Key / - / Missing



Wing / Back Left / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.