


Vehicle details

VIN	YSM4ZPAA0 TF434545	Registration date	11/09/2025	Exterior Color	
Brand	Polestar	Licence Plate	N/A	Odometer	17 803 km
Model	Polestar 4 PA / 200 kW (272 PS)	Condition of the car	Mit Schaden		
Pre-damage		Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details




Removable element

Spare wheel kit	✓
Toolkit	✓
Triangle	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
First aid kit	✓
Inspektion	✓
Ladekabel Starkstrom-Steckdose	✓

Tyres



Exterior

DEKRA Automotive Solutions

1		Part	Tailgate / Boot door	Repair Time	0.60	Part Cost	-
		Position	Back	Repair Cost	46.20€	Net Cost	46.20€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	46.20€		
2		Part	Wing	Repair Time	10.20	Part Cost	845.79€
		Position	Back right	Repair Cost	785.40€	Net Cost	1,835.19€
		Damages	Replace	Paint Time	2.00		
		Comments	-	Paint cost	204.00€		
				Flat Rate	-		

Others

3		Part	Paint preparation	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Net Cost	153.00€
		Damages	Paintworks	Paint Time	1.50		
		Comments	-	Paint cost	153.00€		
				Flat Rate	-		

Estimated repair cost

Total	2,034.39€
--------------	------------------