MACADAM









Volkswagen ID.5: R087XV

Vinnumber:	**WVGZZZE2ZPP508393**	Versionname:	**ID 5 150kW / 77kWh Pro automaat**
First Registrationdate:	**30/12/2022**	Fiscalpower:	
Expertise Mileage:	**125066**	Power Kw:	**150**
Bodytype:		Body colour	**Moonstone Grey unilak**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**844**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Lining Alcantara	
Autom climate control		Rear parking sensors	
Radio multimedia		Hook	
		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 50 / 19 / 103 / T / Aluminium	5,1 mm	Continental	All season
	Right	255 / 50 / 19 / 103 / T / Aluminium	4,2 mm	Continental	All season
Rear	Left	255 / 50 / 19 / 103 / T / Aluminium	4,0 mm	Continental	All season
	Right	255 / 50 / 19 / 103 / T / Aluminium	4,0 mm	Continental	All season

Assistance equipment

Number of charging cables (rapid charge)	**1**

Wing RL, Chemical polution, Polish




Bonnet, Chemical polution, Polish




Door RR, Bad repair, Repair and paint (complete)






Door FR, Bad repair, Repair and paint (complete)





Tailgate / Boot, Dent(s), Repair and paint (complete)







Roof, Dent(s), Paintless dent repair





Onderhoudshistorie van: WVGZZZE2ZPP508393

ALPHABET

Kenteken	R087XV
Merk Model	Volkswagen ID 5 150kW / 77kWh Pro automaat
Brandstofsoort	Elektrisch
Datum deel1	12/30/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/29/26	127,729	Reparatie band(en)
10/29/26	127,729	Sleutelbatterij
1/6/26	104,356	Tankklep
1/6/26	104,356	Tankklepmotor
12/10/24	73,164	Uitlijnen voor en achterwielen
12/10/24	73,164	Vervanging band
5/30/24	52,900	Vervanging band
5/24/24	52,878	Reparatie band(en)
5/24/24	52,878	Vervanging band
6/13/23	17,285	Vervanging band
6/12/23	17,053	Vervanging band