
APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	OPEL
Model / version:	ASTRA SPORTS TOURER DIESEL - 2
Vin:	W0VBD8EU4M8004931
Plate:	1YTW536
Mileage:	130659
First registration:	11/12/2020
Color:	




ADDITIONAL INFORMATION



Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	✓


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	?

PICTURES












































VIN INFORMATION

Commande radio au volant	Boîte manuelle	6 rapports
5 portes	Break	Projecteurs adaptatifs
Projecteurs à LED	Feux arrière à LED	Matière : alliage
Lettre repère (J)	Diamètre avant 16	Diamètre arrière 16
Largeur avant 7,0	Largeur arrière 7,0	Diamètre avant 16
Diamètre arrière 16	Hauteur avant 55	Hauteur arrière 55
Indice de vitesse avant H	Indice de vitesse arrière H	Largeur avant 205
Largeur arrière 205	Climatisation	Accoudoir central avant
Pare-soleil conducteur éclairé	Pare-soleil passager éclairé	Diesel
1496 cm3	1.50 litre	90 kw
122 ch	Alternateur 130 Ampères	Métallisée vernissée

Rétroviseur intérieur jour/nuit automatique	Garnitures tissu et simili-cuir	Volant cuir
Aide au stationnement avant	Aide au stationnement arrière	Caméra avant
Régulateur de vitesse	Affichage lecture des panneaux de signalisation	Lève-vitres arrière électriques
Lunette arrière teintée foncée	Vitres portes arrière teintées foncées	détecteur de pluie essuie-vitre
Attelage avec boule amovible	Assistant maintien de la voie	Contrôle pression des pneus
depuis M8000001/MG000001	siège conducteur ergonomique	éclairage d'ambiance
lampe de lecture ar	système de freinage 15 "	batterie 80 Ah
radio digitale	antenne Diversity	guide d'air réglable

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm		205/55R16 91V	Summer	Aluminium	×
Front right	4 mm		205/55R16 91V	Summer	Aluminium	×
Rear left	4 mm		205/55R16 91V	Summer	Aluminium	×
Rear right	4 mm		205/55R16 91V	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Inner door sill FL	Dent(s) and scratch(es)
2	Door FL	Grooved
3	Alloy rim RL	Grooved
4	Bumper R	Broken
5	Alloy rim FR	Grooved
6	Alloy rim FL	Grooved

Total: 6


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
7	Bodywork	Scratch(es)	✓	×	×

Total: 1


DAMAGES DETAILS

1 - Inner door sill FL - Dent(s) and scratch(es)


2 - Door FL - Grooved



3 - Alloy rim RL - Grooved







4 - Bumper R - Broken












5 - Alloy rim FR - Grooved












6 - Alloy rim FL - Grooved








7 - Bodywork - Scratch(es) - Renta®













SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

14/10/2026 12:00

