MACADAM









SKODA OCTAVIA COMBI: GN-765-VA

Vinnumber:	**TMBJG8NX3PY111545**	Versionname:	**SKODA OCTAVIA COMBI 2.0 TDI 116 DSG7 Sportline VP [5P] bva 7-116CH-6cv (break)**
First Registrationdate:	**5/05/2023**	Fiscalpower:	
Expertise Mileage:	**112305**	Power Kw:	**85**
Bodytype:	**Break**	Body colour	**Blue**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	**HD**	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Rear view camera	
Cruise Control		Seat cover lining	**Lining Other**
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/55/17/95 V**			
	Fr.L.	**Continental: 40%**	Fr.R.	**Continental: 35%**
	Re.L.	**Continental: 15%**	Re.R.	**Continental: 20%**

Tyre profile depth FL	**5.6**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**7.3**
Tyre profile depth RR	**7.0**
Tyre size FL	**205/55 R 17 95 V**
Tyre size FR	**205/55 R 17 95 V**
Tyre size RL	**205/55 R 17 95 V**
Tyre size RR	**205/55 R 17 95 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Seat cover FR, Stain, Cleaning




Seat cover RR, Stain, Cleaning




Alloy rim FR bitone/polychrome, Scratch(es), Acceptable






Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)








Wing RR, Dent(s) and scratch(es), Acceptable







ALPHABET

Historique Maintenance

Immatriculation: **GN-765-VA** Date de 1ère immatriculation: **05/05/2023**

Modèle: **Skoda OCTAVIA COMBI 2.0 TDI 116 DSG7 Sportline VP [5P] bva 7-116CH-6cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
09/01/2026	121.211	CONTITRADE FRANCE	REMPLACEMENT PNEUS 4 SAISONS
15/06/2026	104.222	SAPHIR AUTOMOBILES - GROUPE CAPEL	BALAIS ESSUIE GLACE AV
			REVISION ET AIR ET CARBURANT
			LIQUIDE LAVE GLACE
			ADBLUE
			RECYCLAGE
31/03/2025	73.645	SAPHIR AUTOMOBILES - GROUPE CAPEL	LIQUIDE LAVE GLACE
			BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			LIQUIDE DE FREIN
			ADBLUE
			PLAQUETTES AR RPLT
			PLAQUETTES AV RPLT
			PILE DE CLE RPLT
			RECYCLAGE
			REVISION
16/04/2024	39.715	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
22/02/2024	31.966	AUTO.21 NOGENT-LE-PHAYE	RECYCLAGE
			BALAIS ESSUIE GLACE AV
			REVISION
22/11/2023	19.393	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE