



Volkswagen ID.4 BEV 204pk 77kWh 1st Warmtepomp, Jun-21, 148,454 km



Memo



VIN	WVGZZZE2ZMP017555
Initial registration	17-06-2021
Initial Dutch Registration	17-06-2021
European Type Approval	e1*2018/858*00004*01
Mileage reading / hour counter reading	148,454 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	2024 kg
Doors	5
Power capacity	150 kW
Emission code / Energy label	Z
Wheelbase	277
Loading space	
Load capacity	
RDW details	
Battery capacity	77 kWh
Range	501 km
Battery health	
Charging cables type	2
AC/DC	ACDC
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Gray
Country of registration	The Netherlands
Origin	Lease

Accessories fitted to vehicles

 Rear view camera	 Bluetooth telephone connection	 Metallic paint
 Adaptive cruise control	 Central locking remote control	 Navigation
 Adaptive power steering	 Electronic Stability Program	 Parking sensors rear
 ABS	 Electric windows front	 Parking sensors front + rear
 Audio installation	 Electric windows front + rear	 Start immobiliser
 Automatic air conditioning ECC	 LED lighting	 Heated front seats
 Automatic interior mirror dimmer	 Alloy rims	 Heat reflecting glass

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|-----------------------------|-----------------------------|-----------------------------|
| • Achteropk verkeer waarsch | • Extra getint glas | • Multimedia scherm klein |
| • Achteruitrijcamera | • Forward Collision Warning | • Multimedia-voorbereiding |
| • AEB | • Geluidsisolerend glas | • Navigatiesysteem |
| • Apple CarPl./Android Auto | • Grootlichtassistent | • Oplaadmogelijkheid |
| • Armsteun achter | • Hill hold functie | • Passagiersairbag |
| • Armsteun voor | • Hoofd airbag(s) a. | • Rijstrooksensor met corr. |
| • Band.sp.contr.syst. | • Hoofd airbag(s) v. | • Ruitensproeiers verwarmb. |
| • Bestuurdersairbag | • Hoofdsteunen actief | • Spraakbediening |
| • Bluetooth telefoonvoorb. | • In delen neerkl. achterb. | • Stoel best. hoogte verst. |
| • Buitensp. elekt. inklapb. | • Interieur voorverwarming | • Stof/kunstlederen bekl. |
| • Buitensp. elektr. + verw. | • Keyless start | • Stuurwiel verwarmd |
| • Centrale airbag v. | • LED achterlichten | • Verkeersbord detectie |
| • Connected services | • LED dagrijverlichting | • Vermoeidheids herkenning |
| • Cruise contr.adap Stop&Go | • LED koplampen | • Verstelbaar stuur |
| • DAB radio | • Lederen stuurwiel | • Verwarmde voorruit |
| • Dakrails | • Lichtmetalen velgen 20" | • WiFi voorbereiding |
| • ESP | • Multifunctioneel stuur | • Zij airbag(s) v. |



Comments

No remarks

Vehicle state

MOT due date	17-06-2027	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location	Wheel locks	Not present
			Owner		




Tyres

Rim size	20"		
Wheel	Brand	Type	Tread depth
Front wheel left	Continental	All Season tyre	4 mm
Front wheel right	Continental	All Season tyre	4 mm
Rear wheel left	Continental	All Season tyre	5 mm
Rear wheel right	Continental	All Season tyre	5 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection

Incident	Component	Observations
Unacceptable damage		
1	Bekl zitting v r	dirt (interior)
2	Wheel rim left-rear	scratch(es)
3	Front door left	dent(s)
4	Rear right rim	scratch(es)
5	Rear door right	various damage (see photo)
6	Rear wing right	dent(s)

7		Wheel rim right-front	scratch(es)		
8		Kofferklep spoiler	distorted		
9		Rear bumper	scratch(es)		
10		Roof	dent(s)		
11		Koetswerk	Niet origineel		
					
					
Comments					
No remarks					

Vendor