



Skoda Karoq (UKL): 2BMN687

Vinnumber:	TMBJR7NU0N5030687	Versionname:	Karoq Clever 1.5TSi 150pk/cv 5p
First Registrationdate:	14/01/2022	Fiscalpower:	
Expertise Mileage:	100080	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	plus 23300 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/60/16/99 V				
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				3.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/60 R 16 99 V
Tyre size FR				215/60 R 16 99 V
Tyre size RL				215/60 R 16 95 V
Tyre size RR				215/60 R 16 95 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Seat cover FL, Stain, Cleaning			



Roof liner, Stain, Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Kenteken	2BMN687
Merk Model	Skoda Karoq Clever 1.5TSi 150pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	1/14/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/29/26	92,515	batterij	Vervangen
4/29/26	92,515	Inspectie met olie vervanging (vast in	Uitvoeren
4/29/26	92,515	instelling koplampen	Afstellen
4/29/26	92,515	klein materiaal	
4/29/26	92,515	koelwater vloeistof	Bijvullen/-laden
4/29/26	92,515	luchtfilter	Vervangen
4/29/26	92,515	ruitenswisserrubber achter	Vervangen
4/29/26	92,515	ruitenswisserrubber vooraan	Vervangen
4/29/26	92,515	ruitenswisservloeistof	Bijvullen/-laden
12/15/25	70,205	controle niveaus	Uitvoeren
12/15/25	70,205	olie bijvullen	Bijvullen/-laden
3/10/25	64,211	diagnose	Uitvoeren
2/4/25	63,005	batterij	Vervangen
2/4/25	63,005	bougie	Vervangen
2/4/25	63,005	Inspectie met olie vervanging (vast in	Uitvoeren
2/4/25	63,005	instelling koplampen	Afstellen
2/4/25	63,005	klein materiaal	
2/4/25	63,005	luchtfilter interieur	Vervangen
2/4/25	63,005	remblokken achter	Vervangen
2/4/25	63,005	remblokken vooraan	Vervangen
2/4/25	63,005	remvloeistof	Vervangen
2/4/25	63,005	ruitenswisserrubber achter	Vervangen
2/4/25	63,005	ruitenswisserrubber vooraan	Vervangen
10/31/24	58,211	controle niveaus	Uitvoeren
8/11/23	33,862	instelling koplampen	Afstellen
8/11/23	33,862	klein materiaal	Uitvoeren
8/11/23	33,862	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
8/11/23	33,862	ruitenswisserrubber achter	Vervangen
8/11/23	33,862	ruitenswisserrubber vooraan	Vervangen
1/11/23	18,549	controle niveaus	Uitvoeren
6/29/22	8,830	sleutel lezer/kaart- (startsysteem)	Vervangen