

WAGNER

Audi e-tron '19 BEV




Vehicle information


Make:	Audi	License:	
Gearbox:	Automatic	Body color:	
Model:	e-tron '19 BEV	VIN:	WAUZZZGE0MB032361
Fuel type:	Electric	Power:	300 kW
Version:	e-tron 55 quattro Edition	First registration	05/05/2021
Mileage:	156798 km	N° of doors:	

Damage summary

Front	1
Interior	1
Left	5
Rear	3
Right	3
Roof & others	1

Commercial pictures





Options according to the inspector

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Radio multimedia	Yes	Telephone equipment	Yes		

Damages

Bonnet

Stone chip(s)
Repair and paint (complete)
Front



Boot lid covering R

Scratch(es)
Smart repair
Rear



Bumper moulding R

Deformed / Strained
Repair and paint (complete)
Rear



Bumper R

Scratch(es)
Repair and paint (complete)
Rear



Door FR
Scratch(es)
Repair and paint (partial)
Right



Door frame RL
Dent(s) and scratch(es)
Repair and paint (complete)
Left



Door RL
Scratch(es)
Repair and paint (partial)
Left



Door RR
Scratch(es)
Repair and paint (partial)
Right



Interior
Stain
Cleaning
Interior



Roof

Hail damage
Paintless dent repair (hail)
Roof & others



Roof pillar L

Hail damage
Paintless dent repair (hail)
Left



Roof pillar R

Hail damage
Paintless dent repair (hail)
Right




Wing FL

Dent(s)
Repair and paint (complete)
Left



Wing RL

Scratch(es)
Repair and paint (complete)
Left



Tyres	
	Front Left Summer 255/55/19/111/V Pirelli 6.8 mm Front Right Summer 255/55/19/111/V Pirelli 5.7 mm Rear Left Summer 255/55/19/111/V Pirelli 6.6 mm Rear Right Summer 255/55/19/111/V Pirelli 6.4 mm

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	Yes	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	N/A	User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.