



Expertise

Protocol number: 46397691
Order No. / Reference: 26574168-1
Inspection date: 30 Jun 2026

Manufacturer: Ford

Model: Kuga 2.5 Duratec PHEV TITANIUM

VIN: WF0FXXWPMHNP20802



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV TITANIUM	
Vehicle Identification number	WF0FXXWPMHNP20802
Mileage (Read)	88,553 km
First registration	22 Dec 2022
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Power / Engine displacement	112 kw / 2,488 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufl / 4
Gearbox / Number of gears	Automatic / 1
Type of gearbox	CVT
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Magnetic-Grau (Metallic)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	26 %
Last service on / at	07/2025 at 73,426 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP438402
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	short drive on the company premises	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BTM 00019		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,320 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 106H	Winter tyres on Light alloy	Nokian	5mm / 5mm
2)	225/65 R17 106H	Winter tyres on Light alloy	Nokian	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 102V	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
2)	225/65 R17 102V	Summer tyres on Light alloy	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system
- Electrically adjustable, heated and folding exterior mirrors - painted in body color - with integrated turn signals and ambient lighting
- Tires: Tire repair kit - maximum speed 80 km/h when used
- third brake light
- Roof rails, silver-colored
- 12.3-inch digital instrument panel
- Tachometer
- Driving mode switch with 5 selectable driving modes: Normal, Sport, Eco, Slippery and Unpaved Roads
- Electric front and rear windows with one-touch down function including all windows closed function
- Ford EcoCoach shows the efficiency of current driving behavior.
- Ford Power Start function & Ford Key Free system - keyless locking/unlocking
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot
- Cruise control
- Illuminated glove compartment
- Heated rear window
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Air conditioning with automatic temperature control for driver and passenger side, separately adjustable (2-zone automatic climate control)
- Front and rear headrests (5) height adjustable
- Charging cables for household sockets and for public charging stations
- Steering column, adjustable in height and reach
- Front center console with integrated armrest - 2 front cup holders
- Fog light
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Front and rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist
- Pre-Collision Assist - including forward alert system (FA - Forward Alert) with pedestrian and bicycle detection - active from approx. 5 km/h to 130 km/h, pedestrian and bicycle detection up to approx. 80 km/h.
- Projection lens headlights with LED daytime running lights
- Headlight assistant with day/night sensor
- Seats: Driver and front passenger seats, 8-way manually adjustable including adjustable lumbar support
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Ambient lighting in the front, including front door storage compartment, footwell and cup holder lighting with LED technology
- Passenger airbag deactivation
- Tires: 7 J x 17 light alloy wheels (4) in 5x2-spoke design with 225/65 R 17 tires
- Fabric headliner
- Roof spoiler painted in car color
- Dual exhaust system
- Electronic Stability Program (ESP) with hill start assist, traction control and safety brake assist
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford Easy Fuel - Ford Easy Fuel convenience refueling system (Eliminates the need for a separate internal fuel filler cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- Luggage compartment cover, roller blind, removable
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission (CVT)
- rear window wiper
- Intelligent Protection System (IPS) - Front airbags for driver and front passenger - Front and rear head/shoulder airbags - Side airbags for driver and front passenger - Seat belt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seat belts in all seats, height-adjustable in the front - Warning system for unfastened driver and front passenger seat belts
- LED taillights
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- MyKey key system: individually programmable second key
- Navigation system: Ford navigation system including Ford SYNC 3 - AppLink, Android Auto, Apple CarPlay - 8" touchscreen (20.3 cm screen diagonal) - DAB/DAB+ radio reception (Digital Audio Broadcasting) - 6 speakers - Steering wheel controls - Bluetooth® hands-free calling and audio streaming - 2 USB ports - Voice control for audio and phone - SMS text message reading function - Road map for Europe
- Tire Pressure Monitoring System (TPMS)
- Rear view camera
- Windscreen wipers with rain sensor
- Headlights with delayed shut-off
- Electromechanical, speed-dependent power steering (EPAS - Electric Power Assisted Steering)
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front seats, individually and variably heated
- Power outlet: 12-volt connection in the luggage compartment



- Carpet floor mats front and rear, velour
- Immobiliser

- Central locking with remote control and remote luggage compartment release

Extra equipment

- Swiveling towbar including ESP trailer stabilization
- Electric tailgate, sensor-controlled (opens and closes via foot movement)
- Paint finish: Special metallic paint finish
- Package: Winter - Heated windshield - Heated leather steering wheel
- Safety partition net - including attachment points behind the first and second row of seats
- Mounting points behind the first and second row of seats according to ISO 27955, required for the installation of the safety partition available as an accessory from your participating Ford dealer.
- Package: Winter II - Heated windshield - Heated leather steering wheel - Heated outer rear seats

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door edge - Scratch(es) - Smart repair
2	Bonnet	Insulation lining - Broken / torn - Replace
3	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
4	Rear bumper	Spoiler - Scratch(es) - Replace
5	Wheel / tyres	Tyre - right (3mm Profil) - Does not meet the leasing specifications - Replace
6	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Paint
7	Front bumper	Front bumper - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Side panel - rear right side	Side panel - Soiled - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 2: Bonnet: Insulation lining - Broken / torn - Replace



Damage 2: Bonnet: Insulation lining - Broken / torn - Replace



Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 4: Rear bumper: Spoiler - Scratch(es) - Replace



Damage 5: Wheel / tyres: Tyre - right (3mm Profil) - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyre - right (3mm Profil) - Does not meet the leasing specifications - Replace




Damage 5: Wheel / tyres: Tyre - right (3mm Profil) - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyre - right (3mm Profil) - Does not meet the leasing specifications - Replace



Damage 6: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 6: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 6: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 7: Front bumper: Front bumper - Dent / paintcoat damage - Paint



Damage 7: Front bumper: Front bumper - Dent / paintcoat damage - Paint




Damage 7: Front bumper: Front bumper - Dent / paintcoat damage - Paint



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 3: Side panel - rear right side: Side panel - Soiled - No deduction