



### Ford Focus: J807VV

Vinnumber:	<b>WF0PXXGCHPLY63181</b>	Versionname:	<b>Focus 2.3 EcoBlue 110kW ST-Line X Business wagon automaat</b>
First Registrationdate:	<b>13/11/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>182815</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Frozen White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Opaque</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Parking lot:	<b>579</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

### Options

Number of keys total	<b>2</b>	Rear parking sensors
GPS		Hook
Autom climate control		
Radio multimedia		

### Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 17 / 98 / W / Aluminium	4,5 mm	Goodyear	Summer
	Right	215 / 55 / 17 / 98 / W / Aluminium	4,8 mm	Goodyear	Summer
Rear	Left	215 / 55 / 17 / 98 / W / Aluminium	5,0 mm	Goodyear	Summer
	Right	215 / 55 / 17 / 98 / W / Aluminium	7,5 mm	Goodyear	Summer

### Assistance equipment

Number of charging cables (rapid charge)	<b>0</b>
--	----------

**Bumper RM, Scratch(es), Repair and paint (complete)**



**Bodywork, Chemical polution, Polish**



<b>Kenteken</b>	J807VV
<b>Merk Model</b>	Ford Focus 2.0 EcoBlue 110kW ST-Line X Business wagon automaat
<b>Brandstofsoort</b>	Diesel
<b>Datum deel1</b>	13-11-20

Datum reparatie	Kilometerstand	Reparatie omschrijving
04-09-25	157.215	APK
04-09-25	157.215	Onderhoudsbeurt
04-09-25	157.215	Remschijf + blokken voor
04-09-25	157.215	Vervanging band
02-08-25	155.360	Reparatie band(en)
01-08-25	155.343	Reparatie band(en)
17-09-24	135.480	APK
17-09-24	135.480	Onderhoudsbeurt
17-09-24	135.480	Remvloeistof
13-04-24	125.812	Reparatie band(en)
15-09-23	111.886	APK
15-09-23	111.886	Onderhoudsbeurt
15-09-23	111.886	Remblokken achterzijde
15-09-23	111.886	Ruitenwischerblad(en) achterzijde
15-09-23	111.886	Ruitenwischerblad(en) voorzijde
15-09-23	111.886	Sleutelbatterij
17-04-23	94.192	Reparatie band(en)
06-02-23	85.620	Onderhoudsbeurt
06-02-23	85.620	Remvloeistof
06-02-23	85.620	Vervanging band
12-12-22	68.500	Sleutelbatterij
31-08-22	57.893	Onderhoudsbeurt
31-08-22	57.893	Remblokken voorzijde
31-08-22	57.893	Ruitenwischerblad(en) voorzijde
31-01-22	0	Reparatie band(en)
14-12-21	29.005	Onderhoudsbeurt
14-12-21	29.005	Ruitenwischerblad(en) voorzijde