



BMW X1 (UKL): 2BFK208

Vinnumber:	WBA31AC0205U41625	Versionname:	X1 (F48) 16d sDrive 1.5d 116pk/cv 5p Aut.
First Registrationdate:	3/11/2021	Fiscalpower:	
Expertise Mileage:	86460	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	plus 700 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/17/97 W				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				2.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 97 W
Tyre size FR				225/55 R 17 97 W
Tyre size RL				225/55 R 17 97 W
Tyre size RR				225/55 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Door panel RR, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Replace



Windscreen, Stone chip(s), Replace



Door FL, Dent(s), Acceptable



Door RL, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Acceptable



Door FR, Dent(s), Paintless dent repair



Bodywork, Paint measurement, Acceptable



Roof, Dent(s), Acceptable



Kenteken	2BFK208
Merk Model	BMW X1 (F48) 16d sDrive 1.5d 116pk/cv 5p Aut.
Brandstofsoort	Diesel
Datum deel1	11/3/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/19/25	67,111	BMW/MINI service standaard omvang	Uitvoeren
2/19/25	67,111	klein materiaal	
2/19/25	67,111	service brandstoffilter	Uitvoeren
2/19/25	67,111	service microfilter	Uitvoeren
2/19/25	67,111	service motorolie	Uitvoeren
10/15/24	59,658	BMW/MINI service standaard omvang	Uitvoeren
10/15/24	59,658	klein materiaal	
10/15/24	59,658	remvloeistof	Vervangen
10/15/24	59,658	ruitenswisserrubber achter	Vervangen
10/15/24	59,658	ruitenswisserrubber vooraan	Vervangen
12/19/23	44,133	batterij	Vervangen
12/19/23	44,133	BMW/MINI service standaard omvang	Uitvoeren
12/19/23	44,133	BMW/MINI service voertuig-check	Uitvoeren
12/19/23	44,133	remblokken achter	Vervangen
12/19/23	44,133	remblokken vooraan	Vervangen
12/19/23	44,133	service luchtfilter	Uitvoeren
12/19/23	44,133	service microfilter	Uitvoeren
12/19/23	44,133	service motorolie	Uitvoeren
12/2/22	22,846	BMW/MINI service standaard omvang	Uitvoeren
12/2/22	22,846	BMW/MINI voertuigcontrole	Uitvoeren
12/2/22	22,846	klein materiaal	
12/2/22	22,846	service microfilter	Uitvoeren
12/2/22	22,846	service motorolie	Uitvoeren