

INSPECTION REPORT


End of contract

GENERAL INFO

File	312346
License plate	2BVZ916
Vehicle identification number	W1N2476101W187602
Dossier	2021200006
Make	Mercedes GLB 180d
Mileage	52927
First registration	13/04/2022
client availability date	12/05/2026
inspectionDate	01/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
132	Bumper Rear // Smart Repair Large	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
12	Bumper Front // Smart Repair Large	N
237	Wing Front right / Trim / Replace	N
40	Windshield // Repair	Y
86	Door Front Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	N
110	Wing Rear Left // Smart Repair Small	N
117	Wing Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	N
190	Door Rear Right // Smart Repair Small	Y
213	Door Front Right // Painting	Y

Damage Pictures




Wing Rear Left / Trim / Replace-scratch



Door Rear Right // Smart Repair Small-scratch



Door Front Right // Painting-scratch




Door Front Left // Polish-scratch




Bumper Rear // Painting-scratch



Wing Rear Left // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Windshield // Repair-cracked



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Smart Repair Large-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front // Smart Repair Large-scratch