



PEUGEOT 3008: GM-484-QC

Vinnumber:	VF3MRHNSUNS177015	Versionname:	PEUGEOT 3008 PureTech 130 S&S EAT8 Allure VP [5P] bva 8-130CH-7cv (SUV)
First Registrationdate:	9/03/2023	Fiscalpower:	
Expertise Mileage:	123474	Power Kw:	96
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Tow bar	
Number keys remote	2	Radio	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Semi-leather

Tyres

	225/55/18/102 V			
Summer tyres:	Fr.L.	Michelin: 45%	Fr.R.	Michelin: 40%
	Re.L.	Michelin: 30%	Re.R.	Michelin: 35%
Tyre profile depth FL				5.4
Tyre profile depth FR				5.6
Tyre profile depth RL				6.3
Tyre profile depth RR				6.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Shutter / cover, Broken, Replace			



Door panel RL, Scratch(es), Replace



Seat cover FL, Tear, Replace



Wing trim FL, Scratch(es), Replace



Door FL, Dent(s), Repair and paint (complete)




Door RL, Scratch(es), Paint



Roof pillar L, Dent(s), Repair and paint (complete)



Wing trim RL, Unclashed, Dismount/Mount



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding F, Scratch(es), Paint



Bumper moulding F, Scratch(es), Replace



Grille, Broken, Replace



Wing RR, Dent(s), Repair and paint (complete)



Wing trim RR, Scratch(es), Replace



Door RR, Dent(s), Repair and paint (complete)



Rubber seal for boot lid, Unclassped, Dismount/Mount



Boot lid covering R, Scratch(es), Replace



Bumper moulding R, Scratch(es), Replace



Historique Maintenance

Immatriculation: **GM-484-QC** Date de 1ère immatriculation: **09/03/2023**

Modèle: **Peugeot 3008 PureTech 130 S&S EAT8 Allure VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
24/12/2025	102.647	GARAGE CISCAR	REVISION ET CLIM
	0		COURROIE ACCESSOIRES RPLT
	0		KIT DISTRIBUTION RPLT
24/07/2025	84.027	GARAGE CISCAR	LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAISSUIE GLACE AV AR
	0		CARDAN AVD RPLT
10/12/2024	62.836	GARAGE CISCAR	PLAQUETTES AR RPLT
	0		REVISION
27/06/2024	43.129	GARAGE CISCAR	BALAISSUIE GLACE AV AR
	0		REVISION ET CLIM ET AIR ET BOUGIES
18/01/2024	22.194	AUTO CONCEPT TRUCKS	REVISION