DEKRA

DEKRA Automotive Solutions

Condition Report

Vehicle details

VIN	ZAC5JACL0 SJL80601	Mileage	42 615 km	Engine (Fuel) Type	Petrol
Licence Plate	2HAC579	Registration date	09/05/2025	Engine size	1199
Brand	JEEP	Fuel level	-	Transmission	Manual
Model	Avenger-2023	Car type	PC	Gears	-
Body Type	-	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Gris		

Inspection Details

Inspection date	28/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique




Other technical information

Spare wheel kit	✔
Rear parcel shelf	✔

Tyres

Goodyear 215/60/17 V All seasons 7.0 mm

Goodyear 215/60/17 V All seasons 7.0 mm




Goodyear 215/60/17 V All seasons 7.0 mm

Goodyear 215/60/17 V All seasons 7.0 mm




Damages

1



Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

2



Part	Bonnet
Position	Front
Damages	Chemical deposit
Severity	-
Repair mode	Polishing
Net cost (Excluding VAT)	-

3



Part	Engine soundproofing
Position	-
Damages	Cut
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	146.72€

4



Part	Wing
Position	Front right
Damages	Dented
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	263.88€

DEKRA

DEKRA Automotive Solutions

Condition Report

5



Part	Tailgate / Boot door
Position	Back
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	49.00€

6



Part	Interior boot lining
Position	Back
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	68.00€

7



Part	Door
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

8



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

9



Part	Fabric seat
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Net cost (Excluding VAT)	-

Summary Inspection

Net Price (Exclusing VAT)	527.60€