


2-DKJ-615

2-DKJ-615 · Move! 1.0 TSI 95cv 5v unicolor · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DKJ-615	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ6PR101975
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	Move! 1.0 TSI 95cv 5v unicolor	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	05-04-2023
Color	Black	Odometer	90.665 ^{km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Grey
KW	70	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Delinte	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	5 ^{mm}	Delinte	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type		None				

Damages



Damage Part
Fender - Rear Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Reardoor - Left

Damage Type
small dents / small scratches

Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part
Frontdoor - Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

spoiler FB

Small dent(s)

Plastic Repair

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Frontdoor - Right

Small scratch(es)

Deurgreep

No

Touch-up /
Polish






Damage Part
Reardoor - Right

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Fender - Rear Right

Damage Type
Small scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
spoiler RB

Damage Type
Scratch(es)

Repair Type
Plastic Repair

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Small dent(s)	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No