



Volvo XC 40

Vinnumber:	YV1XZL4VDM2615409	Versionname:	
First Registrationdate:	7/06/2021	Fiscalpower:	
Expertise Mileage:	105489	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2533
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar collapsible
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

235/55/18/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/55 R 18 92 H
Tyre size FR				235/55 R 18 92 H
Tyre size RL				235/55 R 18 92 H
Tyre size RR				235/55 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				259
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	116,69
Seat cover FL, Scratch(es), Smart repair	116,69



Bumper F, Scratch(es), Repair and paint (complete) 0,00



Bumper spoiler F, Scratch(es), Smart repair 0,00



Bumper moulding F, Scratch(es), Acceptable 0,00



Bonnet, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Wing FL, Scratch(es), Acceptable 0,00



Wing trim FL, Scratch(es), Replace 0,00



Bumper trim R, Scratch 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Side window trim FR, Bad repair, Check 0,00



Side window trim RR, Bad repair, Check 0,00



Door RR, Repaired, Acceptable 0,00



Wing trim RR, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Acceptable 0,00

