




## 2-FCF-988



2-FCF-988 · FR 1,0L TSI 110HP DSG KJ75RZ E05 · 30 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-FCF-988	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJXRR116644
Model	Arona	Cylinder Capacity	999 <sup>cm<sup>3</sup></sup>
Model Versions	FR 1,0L TSI 110HP DSG KJ75RZ E05	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	22-03-2024
Color	Blue	Odometer	68.194 <sup>Km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	85	Number Headrests	5

## Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 <sup>mm</sup>	Goodyear	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Rear Left	4 <sup>mm</sup>	Goodyear	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Front Right	2 <sup>mm</sup>	Goodyear	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Rear Right	4 <sup>mm</sup>	Goodyear	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Spare Tire Type	Compressor					

## Damages



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Small scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor - Left	Small scratch(es)	Deurgreep	Touch-up / Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Door-edge chipped	Acceptable	Yes





Damage Part  
Bumper - Front

Damage Type  
Stonechipping

Repair Type  
Acceptable

Acceptable  
Yes



Damage Part  
Hood

Damage Type  
Stonechipping

Repair Type  
Acceptable

Acceptable  
Yes



Damage Part  
Frontdoor - Right

Damage Type  
Small scratch(es)

Repair Type  
Touch-up / Polish

Acceptable  
No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Small scratch(es)	Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No