Renault Trafic !ENGINE BROKEN! 1.6 dCi L1H1 Comfort 95pk EURO6 2017

VF1FL000758841189 · lot Costs



VEHICLE DATA & SPECIFICATIONS

VIN	vf1fl000758841189
First Registration	9/5/2017
Country of Origin	Netherlands
Mileage	186,460 km
Renault Trafic !ENGINE BROK...	Lot: 37Zwolle, NetherlandsFirst registration: September 5, 2017Mileage: 186,460 km100 hp
Front / Right	Back / Left
Place your bid	Auto-bid
Transport costs	Vehicle location:Zwolle, NetherlandsCalculate delivery time and price
Vehicle location	Zwolle, Netherlands
Engine Output HP/PK	100 hp
Power type	Diesel
Cilinder Amount	4
Distribution type	Chain
Engine displacement (cc)	1598
Engine Type	R9M-413 (H4)
Emission norm	Euro 6
Amount of Axles	2
Type of tyres axle 2	Single
Undercarriage	Wheeled
Wheelbase	310 cm
Airco option	airco

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Number of seats	2
Type of cabin	Single
Type of Radio	FM
Empty weight	1800 kg
Registration Date	2017-09-05
M.O.T. approved till	2026-09-15
NAP	Logisch
Gross Vehicle Weight (GVW)	2800 kg
VIN / Serial Number/ Chassisn...	VF1FL000758841189
Brand	Renault
Model	Trafic
Product Group (Tax)	Closed Van
Axle configuration	2002-10-04
Colour	white
Country of origin	NL
Axle capacity 1	1585 kg
Type of drive	FWD
Type extended	Trafic 95pk
Max load capacity	1100 kg
Vehicle Height (cm)	198 cm
Vehicle Length (cm)	500 cm
Vehicle Width (cm)	196 cm
Material floor	Wood
Request Transaction Id	39f9b629-6af4-4f8a-9266-ec2de8626172
Transmission	Manual
Amount of forward gears	6
Type Lights	Halogen
Truck ID	70341161
Lot	37
First registration	September 5, 2017
Transport	Arranged by us, contact us for prices.Own pick-up for transport: 250 fee, collection in Veghel.Technical: ENGINE BROKEN! Not Driveable
October 22, 2026 at 02	18 PM
Peugeot Expert 120pk Closed ...	25-08-2027
Mercedes Vito 109 CDI Functi...	02-10-2027 EURO6 2017
Renault Megane Van 1.5 dCi E...	20-01-2027
Opel Combo 1.3 CDTi Selectio...	10-06-2027

Damage & Condition

All known damages are listed and shown in photos for full transparency.

1 damage reported | Worst: Severe

Engine Bay — Severe

Mechanical

ENGINE BROKEN! Not Driveable



Front / Right



Back / Left












RENAULT
YF1FL000758841189




RENAULT