



BMW X1:

Vinnumber:	WBA31AA0703P13715	Versionname:	
First Registrationdate:	18/01/2022	Fiscalpower:	
Expertise Mileage:	95758	Power Kw:	100
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1110
Fueltype:	Petrol		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

	225/55/17/101 Y			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/55 R 17 101 Y
Tyre size FR				225/55 R 17 201 V
Tyre size RL				225/55 R 17 101 Y
Tyre size RR				225/55 R 17 101 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2769,79
Bonnet, Scratch(es), Repair and paint (complete)	406,19



Bumper spoiler F, Scratch(es), Replace	196,55
--	--------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)	481,95
---	--------



Rear light L, Broken, Replace	238,92
-------------------------------	--------



Rear spoiler, Dent(s), Repair and paint (complete)	280,83
--	--------





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)	491,09
---	--------



Wing trim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Outside rear-view mirror housing R, Scratch(es), Acceptable	0,00
---	------



Roof, Scratch(es), Repair and paint (complete)	674,26
--	--------

