



DS 7 CROSSBACK: GJ-678-MW

Vinnumber:	VR1J45GBUNY586800	Versionname:	DS DS 7 CROSSBACK E-TENSE 4x4 300 PERFORMANCE LINE + VP [5P] bva 8-300CH-11cv (SUV)
First Registrationdate:	22/09/2022	Fiscalpower:	
Expertise Mileage:	66583	Power Kw:	221
Bodytype:	SUV	Body colour:	Light Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Steering wheel leather		Headlights Xenon/LED/Laser	
Seats F heated		Front parking sensors	
Type of climate control	Autom climate control	Rear parking sensors	
		Rear view camera	
		Seat cover lining	Lining Semi-leather
			Lining Alcantara

Tyres

	235/50/19/103 V			
Summer tyres:	Fr.L.	Michelin: 60%	Fr.R.	Michelin: 55%
	Re.L.	Michelin: 60%	Re.R.	Michelin: 70%
Tyre profile depth FL				4.2
Tyre profile depth FR				4.6
Tyre profile depth RL				4.3
Tyre profile depth RR				3.6
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Tyre RR, Out of tolerance, Replace



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Roof pillar L, Dent(s), Repair and paint (complete)



Wing RL, Scratch(es), Acceptable



Bumper F, Scratch(es), Paint



Door RR, Dent(s), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Polish



Historique Maintenance

Immatriculation: **GJ-678-MW** Date de 1ère immatriculation: **22/09/2022**

Modèle: **DS 7 CROSSBACK E-TENSE 4x4 300 PERFORMANCE LINE + VP [5P] bva 8-300CH-11cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
23/04/2026	63.148	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
	0		PERMUTATIONS PNEUS
	0		PERMUTATIONS PNEUS
	0		PERMUTATIONS PNEUS
18/12/2025	56.366	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
04/07/2025	52.251	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
23/06/2025	52.233	STELLANTIS &YOU FRANCE SAS	CARDAN AVD RPLT
	0		REVISION
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
20/11/2024	31.559	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
22/08/2024	27.000	STELLANTIS &YOU FRANCE SAS	BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AV RPLT
	0		REVISION
	0		BOITIER D ALLUMAGE RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
12/04/2024	26.182	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
11/12/2023	21.020	NORAUTO SAS (PRODUIT SPE)	PERMUTATIONS PNEUS
04/09/2023	17.510	PSA RETAIL LES ULIS	REVISION
02/06/2023	11.333	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE
	0		PERMUTATIONS PNEUS
02/06/2023	7.099	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS HIVER