



Peugeot 2008 (UKL): 2CER628

Vinnumber:	VR3USHNKKJ659994	Versionname:	2008 Active Pack 1.2 Puretech S&S 100pk/cv 5p
First Registrationdate:	27/06/2022	Fiscalpower:	
Expertise Mileage:	68666	Power Kw:	74
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	+ 4300 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenance book present		
Type of GPS storage	HD		

Tyres

	215/65/16/98 H			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 2 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				3.0
Tyre profile depth RR				2.0
Tyre size FL				215/65 R 16 98 H
Tyre size FR				215/65 R 16 98 H
Tyre size RL				215/65 R 16 98 H
Tyre size RR				215/65 R 16 98 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Seat cover FR, Stain, Cleaning			



Engine insulation, Hole, Replace



Wing FL, Scratch(es), Polish



Door FL, Dent(s) and scratch(es), Acceptable



Door RL, Dent(s), Acceptable



Roof pillar L, Dent(s), Acceptable



Rear bulkhead lining, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Boot moulding, Scratch(es), Repair and paint (complete)





Bumper moulding R, Scratch(es), Paint



Door FR, Scratch(es), Acceptable



Roof pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Roof, Chemical polution, Polish



Kenteken	2CER628
Merk Model	Peugeot 2008 Active Pack 1.2 Puretech S&S 100pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/27/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/20/26	53,055	50000 km	Uitvoeren
3/20/26	53,055	bougie	Vervangen
3/20/26	53,055	luchtfilter interieur	Vervangen
3/20/26	53,055	oliezeef	Vervangen
3/20/26	53,055	ruitenwisserrubber vooraan	Vervangen
10/1/25	32,922	luchtfilter interieur	Vervangen
10/1/25	32,922	oliezeef	Vervangen
10/1/25	32,922	onderhoud 3e jaar	Uitvoeren
4/23/25	29,649	controle niveaus	Uitvoeren
9/30/24	23,922	25000 km	Uitvoeren
9/30/24	23,922	luchtfilter interieur	Vervangen
9/30/24	23,922	oliezeef	Vervangen
9/30/24	23,922	remvloeistof	Vervangen
9/30/24	23,922	ruitenwisserrubber vooraan	Vervangen
9/27/23	10,960	15000 km	Uitvoeren
9/27/23	10,960	luchtfilter interieur	Vervangen
9/27/23	10,960	oliezeef	Vervangen
9/27/23	10,960	ruitenwisserrubber vooraan	Vervangen