



KMHKN81AFNU042507

Angaben zum Fahrzeug

Halter		Besichtigungszustand	ausreichend
Kennzeichen		Laufleistung (abgelesen)	85.680 km
Hersteller	Hyundai	Restlauf bis Service	3.741 km
Typ/Modell	IONIQ5	HU (Bericht lag vor)	06/2028
Fahrgestellnummer	KMHKN81AFNU042507	Leistung / Hubraum	53 kW / 0 ccm
Erstzulassung	03.01.2022	Polster/Farbe	Stoff/Leder Kombination / Grau-Schwarz
Letzte Wartung		Lackierung	Grün
Kraftstoffart	Elektro	Getriebe	Automatik

Zustandsbericht

Wertmindernde Faktoren

Nr.	Bauteilgruppe	Beschreibung
1	Schweller links	Einstieg - Kratzer - Smart Repair
2	Seitenwand rechts	Einstieg - Delle(n) - sanft instandsetzen
3	Tür vorn links	Tür - Delle(n) - sanft instandsetzen
4	Rad/Reifen	Reifen vorn rechts - Abrieb - erneuern
5	Seitenwand links	Seitenwand - Delle / Lackschaden - instandsetzen und lackieren

Gebrauchsspuren

Nr.	Bauteilgruppe	Beschreibung
1	Lenkanlage	Lenkrad (Gebrauchsspuren)
2	Rad/Reifen	Leichtmetallfelge hinten links - Kratzer
3	Rad/Reifen	Leichtmetallfelge hinten rechts - Kratzer
4	Rad/Reifen	Leichtmetallfelge vorn links - Kratzer
5	Rad/Reifen	Leichtmetallfelge vorn rechts - Kratzer

Fehlteile

Fehlteil

Festgestellte Nachlackierungen

Nr. Ort

Keine feststellbar

Hauptbereifung

Achse	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Verktgl.	Zul.
1	235/55 R19 105V	Continental	Ganzjahresreifen	5mm - 4mm	n.i.O.	i.O.
2	235/55 R19 105V	Pirelli	Ganzjahresreifen	4mm - 4mm	i.O.	i.O.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD KFZ-Prüfstelle
Neuss
Hammer Landstraße 95
41460 Neuss

Besichtigungsdatum: 16.06.2026
Protokollnummer: 46190876
Erstellt durch: Markus Böttcher
Besichtigt durch: Demir



Der Verschleißzustand sowie evtl. Schäden an der Bereifung sind wertmäßig berücksichtigt.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD KFZ-Prüfstelle
Neuss
Hammer Landstraße 95
41460 Neuss

Besichtigungsdatum: 16.06.2026
Protokollnummer: 46190876
Erstellt durch: Markus Böttcher
Besichtigt durch: Demir



Angaben zum Fahrzeug

Hersteller	Hyundai	Besichtigungszustand	ausreichend
Typ/Modell	IONIQ5	Laufleistung (abgelesen)	85.680 km
Fahrgestellnummer	KMHKN81AFNU042507	Erstzulassung	03.01.2022

Angaben zum Auftrag:

Auftragsgemäß erfolgte die Fahrzeugzustandsbewertung in demontagefreien Zustand.

Grundlage dieses Produktes stellt der Leitfaden für Fahrzeugrücknahmen und Bewertungen gemäß des Schadengrenzmusterkatalog des Auftraggebers dar. Die expliziten Feststellungen im Einzelfall trifft der Sachverständige objektiv im Rahmen der vorgegebenen Standards aufgrund eigener Sachkunde.

Fahrzeug-Identifizierung:

Die Fahrzeug-Identifizierungsnummer (FIN) wurde am Fahrzeug abgelesen und die Übereinstimmung im Verlauf der Besichtigung durch den Unterzeichner mit den vorgelegten Unterlagen festgestellt.

Besichtigungsbedingungen:

Die Besichtigungsbedingungen waren zur Beurteilung des Fahrzeuges ausreichend.

Allgemeinzustand:

Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.

Unterschrift Sachverständiger (Markus Böttcher)

Vorliegendes Druckexemplar wurde auf elektronischem Wege erzeugt. Der benannte Sachverständige versichert, dass der Inhalt die von ihm getroffenen Feststellungen korrekt wiedergibt. Es ist ohne Originalunterschrift gültig.

Übersichtsfotos



Abbildung 1: FIN



Abbildung 2: Schräg vorne



Abbildung 3: Schräg vorne



Abbildung 4: Schräg hinten



Abbildung 5: Schräg hinten



Abbildung 6: Montierte Bereifung




Abbildung 7: Innenraum vorne



Abbildung 8: Laderaum



Abbildung 9: Kombiinstrument




Abbildung 10: Kombiinstrument



Abbildung 11: Instrumententafel



Abbildung 12: Dokumente

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD KFZ-Prüfstelle
Neuss
Hammer Landstraße 95
41460 Neuss

Besichtigungsdatum: 16.06.2026
Protokollnummer: 46190876
Erstellt durch: Markus Böttcher
Besichtigt durch: Demir




Abbildung 13: Dokumente

Beschädigungsfotos



Beschädigung #1: Schweller links: Einstieg - Kratzer - Smart Repair



Beschädigung #1: Schweller links: Einstieg - Kratzer - Smart Repair




Beschädigung #2: Seitenwand rechts: Einstieg - Delle(n) - sanft instandsetzen



Beschädigung #1: Schweller links: Einstieg - Kratzer - Smart Repair



Beschädigung #2: Seitenwand rechts: Einstieg - Delle(n) - sanft instandsetzen



Beschädigung #2: Seitenwand rechts: Einstieg - Delle(n) - sanft instandsetzen



Beschädigung #2: Seitenwand rechts: Einstieg - Delle(n) - sanft instandsetzen




Beschädigung #3: Tür vorn links: Tür - Delle(n) - sanft instandsetzen



Beschädigung #3: Tür vorn links: Tür - Delle(n) - sanft instandsetzen



Beschädigung #3: Tür vorn links: Tür - Delle(n) - sanft instandsetzen



Beschädigung #4: Rad/Reifen: Reifen vorn rechts - Abrieb - erneuern



Beschädigung #4: Rad/Reifen: Reifen vorn rechts - Abrieb - erneuern

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD KFZ-Prüfstelle
Neuss
Hammer Landstraße 95
41460 Neuss

Besichtigungsdatum: 16.06.2026
Protokollnummer: 46190876
Erstellt durch: Markus Böttcher
Besichtigt durch: Demir



Beschädigung #5: Seitenwand links: Seitenwand - Delle / Lackschaden - instandsetzen und lackieren



Beschädigung #5: Seitenwand links: Seitenwand - Delle / Lackschaden - instandsetzen und lackieren



Beschädigung #5: Seitenwand links: Seitenwand - Delle / Lackschaden - instandsetzen und lackieren



Beschädigung #5: Seitenwand links: Seitenwand - Delle / Lackschaden - instandsetzen und lackieren



**COMPLETE VEHICLES
CERTIFICATE OF CONFORMITY**

Übereinstimmungsbescheinigung
Πιστοποιητικό Συμμόρφωσης
Certificat de Conformité
Certificate of Conformity
Certificato di Conformità
Conformiteitscertificaat
Świadectwo Zgodności
Certifikat o składności
Certificado de Conformidad

046CC0118238



www.PS-Team.de

Part 1

The undersigned C. S. PARK GENERAL MANAGER hereby certifies that the vehicle:

0.1. Make (Trade name of manufacturer):	HYUNDAI
0.2. Type:	NE
- Variant:	F5E32
- Version:	E11A11
0.2.1. Commercial name(s):	IONIQ5
0.2.3. Identifiers:	
0.2.3.1. Interpolation family's identifier:	IP-0931049-KMH-1
0.2.3.2. ATCT family's identifier:	-
0.2.3.3. PEMS family's identifier:	-
0.2.3.4. Roadload family's identifier:	RL-0931049-KMH-1
0.2.3.5. Roadload Matrix family's identifier:	-
0.2.3.6. Periodic regeneration family's identifier:	-
0.2.3.7. Evaporative test family's identifier:	-
0.4. Vehicle category:	M1
0.5. Company name and address of manufacturer:	
Hyundai Motor Company, 12 Heolleung-ro, Seocho-gu, Seoul, Korea	
0.6. Location and method of attachment of the statutory plates:	
On the left hand B-post, bonded	
Location of the vehicle identification number:	
Under the right front seat	
0.9. Name and address of the manufacturer's representative:	
Hyundai Motor Europe Technical Center GmbH; Hyundai Platz, 65428 Rüsselsheim, Germany	
0.10. Vehicle identification number:	KMHKN81AFNU042507
0.11. Date of manufacture of the vehicle:	06.10.2021

conforms in all respects to the type described in approval e9*2018/858*11054*01 granted on 05.04.2021
and can be permanently registered in Member States having right hand traffic and using metric
units for the speedometer and metric units for the odometer

Place, Date and Signature

HMC

16.12.2021

Part 2

General construction characteristics

1. Number of axles:	2 and wheels 4
3. Powered axles (number, position, interconnection):	1, Rear
3.1. Specify if the vehicle is non-automated/automated/fully automated	non-automated

Main dimensions

4. Wheelbase:	3000 mm
4.1. Axle spacing:	1-2: 3000 mm 2-3: mm 3-4: mm
5. Length:	4635 mm
6. Width:	1890 mm
7. Height:	1605 mm

Masses

13. Mass in running order:	1985 kg
13.2. Actual mass of the vehicle:	2021 kg
16. Technically permissible maximum masses	
16.1. Technically permissible maximum laden mass:	2430 kg
16.2. Technically permissible mass on each axle:	1. 1280 kg 2. 1370 kg
16.4. Technically permissible maximum mass of the combination:	4030 kg
18. Technically permissible maximum towable mass in case of:	
18.1. Drawbar trailer:	- kg
18.3. Centre-axle trailer:	1600 kg
18.4. Unbraked trailer:	750 kg
19. Technically permissible maximum static vertical mass at the coupling point:	100 kg

3770367

GN020239

Power plant

20. Manufacturer of the engine: Hyundai Mobis
21. Engine code as marked on the engine: EM17
22. Working principle: -
23. Pure electric: yes
- 23.1. Class of Hybrid [electric] vehicle: no
24. Number and arrangement of cylinders: - -
25. Engine capacity: - cm3
26. Fuel: Electricity
- 26.1. Mono fuel/Bi fuel/Flex fuel/Dual-fuel: -
- 26.2. (Dual-fuel only)
27. Maximum power
- 27.1. Maximum net power: - kW at -min-1
(internal combustion engine) :
- 27.3. Maximum net power: 160.00 kW (electric motor)
- 27.4. Maximum 30 minutes power: 53.00 kW (electric motor)
28. Gearbox (type): Automatic
- 28.1. Gearbox ratios

1st gear	2nd gear	3rd gear	4th gear	5th gear	6th gear	7th gear	8th gear
-	-	-	-	-	-	-	-

28.1.1. Final drive ratio: -

28.1.2. Final drive ratios

1st gear	2nd gear	3rd gear	4th gear	5th gear	6th gear	7th gear	8th gear
-	-	-	-	-	-	-	-

Maximum speed

29. Maximum speed: 185 km/h

Axles and suspension

30. Axle(s) track: 1. 1638 mm 2. 1647 mm
35. Fitted tyre/wheel combination/energy efficiency class of rolling resistance coefficients (RRC) and tyre category used for CO2 determination:
- Axle1 : 235/55R19 105W 7.5Jx19/ET49.5 / A/C1
- Axle2 : 235/55R19 105W 7.5Jx19/ET49.5 / A/C1

Brakes

36. Trailer brake connections -

Bodywork

38. Code for bodywork: AF(multi-purpose vehicle)
40. Colour of vehicle: green
41. Number and configuration of doors: 5; 2 left, 2 right, 1 rear
42. Number of seating positions (including the driver): 5
- 42.1. Seat(s) designated for use only when the vehicle is stationary: -
- 42.3. Number of wheelchair user accessible position: -

Environmental performances

46. Sound level
- Stationary: - dB(A) at engine speed : - min-1
- Drive-by: 69,00 dB(A)
47. Exhaust emission level: Euro AX
- 47.1. Parameters for emission testing of Vind
- 47.1.1. Test mass, kg: 2141
- 47.1.2. Frontal area, m2: 2.619
- 47.1.2.1. Projected frontal area of air entrance of the - the front grille, cm2:
- 47.1.3. Road load coefficients
- 47.1.3.0. f0, N: 124.6
- 47.1.3.1. f1, N/(km/h): 1.108
- 47.1.3.2. f2, N/(km/h) 2: 0.03253
- 47.2. Driving cycle
- 47.2.1. Driving Cycle class: 3b
- 47.2.2. Downscaling factor (fdsc): -
- 47.2.3. Capped speed: no
48. Exhaust emissions: EC715/2007*2018/1832AX

1.2. Test procedure: Type 1 (NEDC average values, WLTP highest values) or WHSC (EURO VI)

- CO: - mg/km
- THC: - mg/km
- NMHC : - mg/km
- NOx: - mg/km
- THC+NOx: - mg/km
- NH3 : -
- Particulates (mass) : - mg/km
- Particles (number) : -

2.2. test procedure: WHTC (EURO VI)

- 48.1. Smoke corrected absorption coefficient: -(m-1)

48.2. Declared maximum RDE values

- Complete RDE trip: Urban RDE trip:
- NOx: -mg/km -mg/km
- Particles (number) : - -

49. CO2 emissions/fuel consumption/electric energy consumption:

1. All power trains, except pure electric vehicles

NEDC Values	CO2 emissions	Fuel consumption
Urban conditions:	consedelegalei g/km	consedelegalei l/100 km
Extra-urban conditions :	consedelegalei g/km	consedelegalei l/100 km
Combined:	consedelegalei g/km	consedelegalei l/100 km
Weighted, combined :	- g/km	- l/100 km
Deviation factor	-	-
Verification factor	-	-

2. Pure electric vehicles and OVC hybrid electric vehicles

Electric energy consumption (weighted, combined)	Wh/km
Electric range	km

3. Vehicle fitted with eco-innovation(s): -
- 3.1. General code of the eco-innovation(s): -
- 3.2. Total CO2 emissions savings due to the eco-innovation(s)
- 3.2.1. NEDC savings: - g/km
- 3.2.2. WLTP savings: - g/km

4. All power trains, except pure electric vehicle, under Commission Regulation(EU) 2017/1151

WLTP values	CO2 emissions	Fuel consumption
Low:	- g/km	- l/100 km
Medium:	- g/km	- l/100 km
High:	- g/km	- l/100 km
Extra High	- g/km	- l/100 km
Combined:	- g/km	- l/100 km
Weighted, combined	- g/km	- l/100 km

5. Pure electric vehicles and OVC hybrid electric vehicles, under Commission Regulation (EU) 2017/1151

5.1. Pure electric vehicles

Electric energy consumption	168 Wh/km
Electric range	481 km
Electric range city	686 km

5.2. OVC hybrid electric vehicles

Electric energy consumption (ECAC,weighted) :	- Wh/km
Electric range (EAER)	- km
Electric range city (EAER city)	- km

Miscellaneous

51. For special purpose vehicles: designation in accordance with point 5 of Part A of Annex I to Regulation (EU) 2018/858 of the European Parliament and of the Council:

52. Remarks: 7:1647*13:1985*35:235/55R19 105W,LM-Rad,7.5Jx19/ET49.5*

MOBILITY CONCEPT

LVV Nr 5985281
Hersteller Hyundai
Model IONIQ 5
Variante Techniq 72.6 kWh
Listenpreis 25.579,71
VIN KMHKN81AFNU042507
Erstzulassungsdatum 3.1.2022
Kennzeichen NE-DX 420E

Schadensfälle der int. Belegnummer: 368933

09.07.2026

Schadennummer	Unfalldatum	Beschädigung	Schadenhöhe in EUR
2023111615	15.08.2023	Fahrzeug rundherum beschädigt	
2023111326	15.08.2023	Fahrzeug rundherum beschädigt	1.428,17
2024111568	22.07.2024	kein Schaden an Fahrzeug	
2026107251	07.05.2026	Windschutzscheibe gerissen	2.460,78
2026107879	17.05.2026	Fahrerseite Kotflügel vorne Fahrerseite Tür vorne	

- Seite 1 von 1 -