



BMW 118: X670SZ

Vinnumber:	WBA7K310707N90887	Versionname:	118iA 100kW
First Registrationdate:	24/01/2024	Fiscalpower:	
Expertise Mileage:	143075	Power Kw:	100
Bodytype:		Body colour	Saphirschwarz Metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	359
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining semi-leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 17 / 94 / Y / Aluminium	5,2 mm	Goodyear	Summer
	Right	225 / 45 / 17 / 94 / Y / Aluminium	5,7 mm	Goodyear	Summer
Rear	Left	225 / 45 / 17 / 94 / Y / Aluminium	5,0 mm	Goodyear	Summer
	Right	225 / 45 / 17 / 94 / Y / Aluminium	5,0 mm	Goodyear	Summer

Assistance equipment

Wing FL, Stone chip(s), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Replace



Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

