



Ford Kuga (UKL): 2CAB327

Vinnumber:	WF0FXXWPMHNS88370	Versionname:	Kuga Vignale 2.5i PHEV 225pk/cv 5p Aut.
First Registrationdate:	6/05/2022	Fiscalpower:	
Expertise Mileage:	94242	Power Kw:	112
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	245/45/20/103 Y			
Summer tyres:	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL	6.0			
Tyre profile depth FR	6.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	245/45 R 20 103 Y			
Tyre size FR	245/45 R 20 103 Y			
Tyre size RL	245/45 R 20 103 Y			
Tyre size RR	245/45 R 20 99 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	258			
Tyre make FR	258			
Tyre make RL	256			
Tyre make RR	256			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	0		

Windscreen, Repaired, Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Kenteken	2CAB327
Merk Model	Ford Kuga Vignale 2.5i PHEV 225pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	5/6/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/15/25	85,011	oliewissel	Uitvoeren
12/15/25	85,011	oliezeef	Vervangen
2/4/25	64,445	68000 km	Uitvoeren
2/4/25	64,445	luchtfilter	Vervangen
2/4/25	64,445	oliezeef	Vervangen
5/30/24	4,645	diagnose	Uitvoeren
4/2/24	43,876	45000 km	Uitvoeren
4/2/24	43,876	luchtfilter interieur	Vervangen
4/2/24	43,876	oliezeef	Vervangen
4/2/24	43,876	remvloeistof	Vervangen
12/7/23	35,655	batterij	Vervangen
6/28/23	24,428	25000 km	Uitvoeren
6/28/23	24,428	luchtfilter interieur	Vervangen
6/28/23	24,428	oliezeef	Vervangen
10/18/22	8,990	controle niveaus	Uitvoeren