

## Vehicle details

|                   |                    |              |                                  |                           |                |
|-------------------|--------------------|--------------|----------------------------------|---------------------------|----------------|
| VIN               | KNAC381CP N5056729 | Brand        | KIA                              | Maintenance date          | -              |
| Licence Plate     |                    | Model        | EV6 77.4kWh Plus Advanced AWD 5d | Maintenance mileage       | -              |
| Registration date | 13/07/2022         | Year         | 2022                             | Exterior Color            | Green Metallic |
| Odometer          | 182 926 km         | Engine size  | -                                | Interior Color            | Black          |
| Fuel              | Electric           | Body Type    | -                                | Next technical inspection | -              |
| Seats             | -                  | Transmission | Automatic                        | CO2                       | -              |
| Doors             | 5                  | Gears        | -                                |                           |                |

## Inspection Details


|                 |            |                 |  |
|-----------------|------------|-----------------|--|
| Inspection date | 17/07/2026 | Inspection loc. |  |
|-----------------|------------|-----------------|--|



| Generic equipment            | Removable element  | Technical Document        |
|------------------------------|--------------------|---------------------------|
| Automated air-conditioning ✓ | Spare wheel kit ✓  | User manual ✓             |
| Cruise control ✓             | Load cover ✓       | Warranty booklet ✓        |
| Leather ✓                    | Vehicle charger ✓  | Spare key ✓               |
| GPS system ✓                 | Wireless charger ✗ | Remote key ✓              |
| Sliding roof ✓               |                    | Sat Nav CD ROM Software ✓ |
| Alloy wheel rims ✓           |                    |                           |
| Automatic Gearbox ✓          |                    |                           |
| Heating seats ✓              |                    |                           |
| Electric seats ✓             |                    |                           |
| Tow ✓                        |                    |                           |
| Metallic paint ✓             |                    |                           |
| Central locking ✓            |                    |                           |
| Electric windows ✓           |                    |                           |
| 4x4 ✓                        |                    |                           |
| Park Distance Control ✓      |                    |                           |
| Audio System ✓               |                    |                           |
| Led lighting ✓               |                    |                           |

## Tyres

Pirelli 255/55/20 Summer 3.0 mm



Pirelli 255/55/20 Summer 3.0 mm



Pirelli 255/55/20 Summer 4.0 mm



Pirelli 255/55/20 Summer 4.0 mm

## Exterior

|   |                                                                                      |                                                        |                                                                           |
|---|--------------------------------------------------------------------------------------|--------------------------------------------------------|---------------------------------------------------------------------------|
| 2 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Step plate<br>Front left<br>Dent & Chips<br>-<br>For info                 |
| 3 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Alloy wheel 20"<br>Front left<br>Scratched<br>-<br>Lumpsum repair         |
| 4 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Tailgate / Boot door<br>-<br>Dented<br>Diameter (mm) > 20<br>Smart Repair |
| 5 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Wing<br>Back right<br>Dented<br>Diameter (mm) > 20<br>Smart Repair        |
| 6 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Door<br>Front right<br>Dent & Chips<br>-<br>Repair                        |
| 7 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Alloy wheel 20"<br>Front right<br>Scratched<br>-<br>Lumpsum repair        |
| 8 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Bonnet<br>-<br>Stone impact<br>-<br>For info                              |
| 9 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Bumper<br>Front right<br>Scratched<br>-<br>Repair                         |

Others

|   |                                                                                   |             |                  |
|---|-----------------------------------------------------------------------------------|-------------|------------------|
| 1 |  | Part        | Wireless charger |
|   |                                                                                   | Position    | -                |
|   |                                                                                   | Damages     | Missing          |
|   |                                                                                   | Severity    | -                |
|   |                                                                                   | Repair mode | For info         |