



Tesla

BEV 75KWH LONG RANGE AUTO 4WD

VIN: LRWYGCEK4NC341656

Description



Registration number

Registration date

Odometer

14/06/2022

149363 km

Color

Year

Upholstery

Pearl White Multi-coat

-

-

Number of doors

Number of seats

Generation




5

-

-

Max power

378 KW



Statement details

Inspection loc

Statement date

04/08/2026

Inspection approval date

05/08/2026

Control

Detected issues

Engine / Sound

✓ Ok


Vehicle leak proofness

✓ Ok

Exhaust / Clarity

✓ Ok

Defects & corrections

#	Element	Defect	Correction
001	Registration certificate2 / -	Missing	Replace
			
002	Rim / Front Left Material : Aluminium alloy /Rim/Tyre diameter : 19 " /Surface : Painted	Scratched	Acceptable
			
003	Rim / Front Right Material : Aluminium alloy /Rim/Tyre diameter : 19 " /Surface : Painted	Scratched	Repair
 			
004	Rim / Back Right Material : Aluminium alloy /Rim/Tyre diameter : 19 " /Surface : Painted	Broken	Replace
 			
005	Rim / Back Left Material : Aluminium alloy /Rim/Tyre diameter : 19 " /Surface : Painted	Scratched	Repair
  			
006	Wheel trim / Back Left Rim/Tyre diameter : 19 "	Scratched	Replace
  			
007	Exterior door mirror shell / Left	Scratched	Acceptable



008 Door / Back Left

Dent

Smart repair



009 Wing / Back Left

Scratched

Acceptable



010 Tailgate / Boot door / -
Windowed : Yes

Scratched

Acceptable



011 Bumper / Back
Painted : No

Scratched

Acceptable



Loose Items

- ☒ Rear parcel shelf
- ☐ Tyre repair kit complete
- ☐ Document holder
- ☐ Registration certificate owner
- ☐ Toolkit

- ☐ Remote key
- ☐ Security Kit
- ☒ Triangle
- ☐ Warranty booklet
- ☐ Hook /Hicth ball

- ☐ Remote control
- ☐ Compressor tyre repair kit
- ☒ First aid kit
- ☐ User manual
- ☐ Jack



Main set of tyres

Front Left	PIRELLI	255 / 45 / 19 / Summer	3 mm
Front Right	PIRELLI	255 / 45 / 19 / Summer	3 mm
Back Left	CONTINENTAL	255 / 45 / 19 / Summer	4 mm
Back Right	CONTINENTAL	255 / 45 / 19 / Summer	4 mm

Comments

Appendices : SOH Report



All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.