

INSPECTION REPORT



End of contract

GENERAL INFO

File	313706
License plate	2BXJ916
Vehicle identification number	WBA31BK050CK34245
Dossier	2022 017 047
Make	BMW 520e 150kW Aut
Mileage	35369
First registration	28/04/2022
client availability date	26/05/2026
inspectionDate	06/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
66	Wing Front Left // Polish	Y
80	Door Front Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
186	Wing Rear Right // Polish	Y
216	Door Front Right // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N

Damage Pictures



Door Front Left // Smart Repair Small-scratch



Wing Front Left // Polish-scratch




Wheel Alloy Front Left // Repair-scratch



Bumper Front // Painting-scratch



Wing Rear Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Front Right // Polish-scratch



Bumper Rear // Polish-scratch