



CUPRA FORMENTOR: GF-377-WZ

Vinnumber:	VSSZZZKMZNR057940	Versionname:	CUPRA FORMENTOR 1.4 e-HYBRID 204ch DSG6 Business Edition VP [5P] bva 6-204CH-8cv (SUV)
First Registrationdate:	19/04/2022	Fiscalpower:	
Expertise Mileage:	57524	Power Kw:	150
Bodytype:	SUV	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Sun Roof electric	
GPS big screen color		Panoramic roof	
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Headlights Xenon/LED/Laser	
Steering wheel leather		Front parking sensors	
Type of climate control	Autom climate control	Rear parking sensors	
		Rear view camera	
		Seat cover lining	Lining Leather

Tyres

	245/45/18/96 W			
Summer tyres:	Fr.L.	Continental: 30%	Fr.R.	Continental: 30%
	Re.L.	Continental: 30%	Re.R.	Continental: 40%
Tyre profile depth FL				6.1
Tyre profile depth FR				6.2
Tyre profile depth RL				6.1
Tyre profile depth RR				5.6
Tyre size FL				245/45 R 18 96 W
Tyre size FR				245/45 R 18 96 W
Tyre size RL				245/45 R 18 96 W
Tyre size RR				245/45 R 18 96 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Jack	No
Sunroof cover, Not functioning (well), Check	



Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Bumper spoiler F, Deformed / Strained, Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Paint



Jack, Missing, Repair/replace (lump sum)



Historique Maintenance

Immatriculation: **GF-377-WZ** Date de 1ère immatriculation: **19/04/2022**

Modèle: **CUPRA FORMENTOR 1.4 e-HYBRID 204ch DSG6 Business Edition VP [5P] bva 6-204CH-8cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
27/05/2026	116.978	CONTITRADE FRANCE LA CROIX ST OUEN	REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
31/03/2026	113.188	VGRF GRAND OUEST VEZIN LE COQUET	REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		RECYCLAGE
31/03/2026	113.188	VGRF GRAND OUEST VEZIN LE COQUET	CONTROLE TECHNIQUE
01/09/2025	95.648	VGRF GRAND OUEST	BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
	0		LIQUIDE LAVE GLACE
	0		REVISION ET CLIM
	0		BALAI ESSUIE GLACE AR