DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	W0V7H9EN4 P4349493	Registration date	20/06/2024	Exterior Color	Unknown
Brand	OPEL	Licence Plate	KO-VK 818	Odometer	31 992 km
Model	CROSSLAND 1.5 Diesel 81kW Elegance				

Inspection Details

Arrival Date	19/08/2026	Inspection ID	7136267	Inspection date	25/08/2026
Assign Date	19/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys AKB Kitzingen




























Generic equipment

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

DEKRA


DEKRA Automotive Solutions

Appraisal Report

Tyres

Bridgestone 195/60/16 H Summer 6.0 mm

Bridgestone 195/60/16 H Summer 6.0 mm



Bridgestone 195/60/16 H Summer 6.0 mm


Bridgestone 195/60/16 H Summer 6.0 mm



Winter kit

Falken 195/60/16 H Winter 6.0 mm

Falken 195/60/16 H Winter 6.0 mm



Falken 195/60/16 H Winter 6.0 mm

Falken 195/60/16 H Winter 6.0 mm



Exception / Damage

1



Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

2



Part	Bonnet	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

3



Part	Windscreen	Repair Time	1.70	Part Cost	458.03€
Position	Front	Repair Cost	238.00€	Gross Cost	696.03€
Damages	Broken	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**696.03€**

4



Part	Fixing glue kit	Repair Time	-	Part Cost	98.05€
Position	Front	Repair Cost	-	Gross Cost	98.05€
Damages	Broken	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 14.71
Repair mode	Replace	Flat Rate	-	**Net Cost**	**83.34€**

Summary Inspection

Gross Price	794.08€	Depreciation	-14.71€	Net Price	779.37€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	1.70	238.00€	-	-	238.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	556.08€	2.64 %	-14.71€	541.37€
Flat Rate	0.00€	-	-	0.00€