



PEUGEOT 308: 3343-LWP

Vinnumber:	VR3FBYH2TNY506635	Versionname:	5P Allure BlueHdi 130 S&S EAT8 berlina con portón
First Registrationdate:	25/02/2022	Fiscalpower:	96kW 5P automática
Expertise Mileage:	145110	Power Kw:	
Bodytype:	Berline	Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
GPS big screen color		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	225/45/17/94 W			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 17 94 W
Tyre size FR				225/45 R 17 94 W
Tyre size RL				225/45 R 17 94 W
Tyre size RR				225/45 R 17 94 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment


Repair kit	Yes
Boot lid covering R, Scratch(es), Replace	



Registration document, Missing, Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wheel bolt cover RL, Missing, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Acceptable



Tyres, No damage, Check



