



BMW 3			
Vinnumber:	WBASP51010FL20550	Versionname:	330e (215 kW)
First Registrationdate:	9/04/2021	Fiscalpower:	
Expertise Mileage:	176429	Power Kw:	215
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2510
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Maintenance	18000.0		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		
Type of GPS storage	HD		
Limited Technical Inspection			
Tyres			
225/45/18/95 Y			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R. Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R. Michelin: 4 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			225/45 R 18 95 Y
Tyre size FR			225/45 R 18 95 Y
Tyre size RL			255/40 R 18 99 Y
Tyre size RR			255/40 R 18 99 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			261
Tyre make FR			261
Tyre make RL			261
Tyre make RR			261
Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			685,51
Bumper F, Scratch(es), Spot repair			148,33



Bumper moulding F, Scratch(es), Replace	128,76
---	--------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------




Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Bumper R, Dent(s) and (es), Acceptable	0,00
--	------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Wing RR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Sill trim R, Scratch(es), Acceptable	0,00
--------------------------------------	------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------

