VEHICLE REPORT

IT · 04/11/2026
2026-11-04 09:44

VIN: Targa: Merchant:


VEHICLE DETAILS

Targa		First Registration	**2018-12-28**
Marca	N/A	Mileage	N/A
Modello e Allestimento		Keys	N/A
VIN		Owners	**4**
Merchant		Seats	**5**
Branch		Previous Use	**AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE**
KW	**180**	VAT	N/A
CC	**0**	Country	**IT**
Fuel	**BENZ**	Euro	**EURO6**
GPL	**Non presente**	Cambio	**Non presente**
Gancio	N/A		

CAR PHOTOS (77)


Front.


Additional photos (optional)


Additional photos (optional)


Interior front


Underbody view.


Underbody.


Left side front


Front left


Rear


Engine compartment


Interior front.


Engine compartment


Engine compartment


Engine compartment.


Interior front


Center console and dashboard


Center console and dashboard


Interior front


Center console and dashboard


Center console and dashboard


Navigation on.


Interior front


Speedometer with started engine


Interior front


Front door left


Interior rear


Interior rear


Interior front


Interior rear


Interior front.


Interior front.


Interior front


Interior front


Front door left


Interior rear


Rear door left


Front door left


Left side rear


Left side front


Left side front


Front left


Front left


Hood


Front


Front left


Front left


Left side front



Left side front


Front door left


Left side front


Front door left


Left side front


Left side rear.


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Left side front


Front left


Left side front


Rear


Center console and dashboard


Trunk


Trunk


Rear


Rear


Front left


Left side front


Left side front

Front

CARFAX **Vehicle History Report**

2019 PORSCHE MACAN

Vehicle reference:
WP1ZZZ95ZKLB00311

Body type:
Estate

Engine size:
1984 cm³

Total system power:
180 kW / 245 hp

Combustion engine power:
180 kW / 245 hp

Gearbox type:
Automatic

Fuel type:
Petrol

Quick check

Damage
This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

Import
No data available

Legend


- No issues reported or indicated
- Valuable Information
- Requires attention
- Data unavailable

Damage overview

04/2023

Affected area (6):

Location reference, does not indicate the extent of the damage.



- Left
- Left front
- Left rear
- Rear
- Right
- Right rear

Reported in
Italy

Damage type/cause
Not available

Damage severity:


Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

06/2023

Affected area (3):

Location reference, does not indicate the extent of the damage.



- Rear
- Right
- Right rear

Reported in
Italy

Damage type/cause
Not available

Damage severity:

Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

Owners BETA

No owners found: No owners found

Technical details

Engine and performance

Fuel type
Petrol

Combustion engine power
180 kW / 245 hp

Environment and consumption

EU emission standard
Euro 6

Weight

Gross vehicle weight
2 510 kg

Other information

European vehicle category
M1

EU standard code
e13*07/46*1165*10

Number of doors
5

Number of seats
5

History information

Date	Mileage	Event
04/2023		**Damage reported in Italy**

06/2023	**Damage reported in Italy**

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our Terms and conditions.