MACADAM











Mercedes GLA-Klasse (UKL): 2CMB999

Vinnumber:	**W1N2477101J362396**	Versionname:	**GLA180d Business Solution 2.0d 116pk/cv 5p 8G-DCT**
First Registrationdate:	**13/09/2022**	Fiscalpower:	
Expertise Mileage:	**72565**	Power Kw:	**85**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**B in 32 days**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**235/55/18/100 W**			
	Fr.L.	**Pirelli: 6 mm**	Fr.R.	**Pirelli: 6 mm**
	Re.L.	**Continental: 6 mm**	Re.R.	**Continental: 6 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**235/55 R 18 100 W**
Tyre size FR	**235/55 R 18 100 W**
Tyre size RL	**235/55 R 18 100 W**
Tyre size RR	**235/55 R 18 100 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**264**
Tyre make FR	**264**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)











Windscreen, Not original part, Remove lettering




Bumper moulding F, Scratch(es), Acceptable





Outside rear-view mirror housing L, Scratch(es), Acceptable




Alloy rim RL polished, Scratch(es), Acceptable





Central pillar L, Dent(s), Acceptable




Boot lid covering R, Scratch(es), Replace




Alloy rim RR polished, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable




Central pillar R, Dent(s), Acceptable




Onderhoudshistorie van: W1N2477101J362396

ALPHABET

Kenteken	2CMB999
Merk Model	Mercedes GLA180d Business Solution 2.0d 116pk/cv 5p 8G-DCT
Brandstofsoort	Diesel
Datum deel1	9/13/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/5/26	70,709	klein materiaal	
6/5/26	70,709	vergrendelingsmotor (deur, koffer, tank	Vervangen
3/4/26	66,307	klein materiaal	
3/4/26	66,307	ruitenwisserrubber vooraan	Vervangen
9/9/25	57,486	brandstoffilter	Vervangen
9/9/25	57,486	klein materiaal	
9/9/25	57,486	luchtfilter	Vervangen
9/9/25	57,486	mercedes assyst a	Uitvoeren
9/9/25	57,486	remblokken vooraan	Vervangen
10/4/24	45,906	dakgel. smeren	Uitvoeren
10/4/24	45,906	klein materiaal	
10/4/24	45,906	mercedes assyst b	Uitvoeren
10/4/24	45,906	remvloeistof	Vervangen
10/4/24	45,906	ruitenwisserrubber vooraan	Vervangen
6/3/24	39,930	controle niveaus	Uitvoeren
9/25/23	26,515	klein materiaal	Uitvoeren
9/25/23	26,515	mercedes assyst a	Uitvoeren
9/25/23	26,515	ruitenwisserrubber achter	Vervangen
9/25/23	26,515	ruitenwisserrubber vooraan	Vervangen