



Expertise

Protocol number: 46527089  
Order No. / Reference: 26496746  
Inspection date: 9 Jul 2026

Manufacturer: Mercedes-Benz  
VIN: W1N9N0CB1PJ082386

Model: EQA 250+ Progressive



| Vehicle details                         |                             |
|-----------------------------------------|-----------------------------|
| Manufacturer / Type / Model / Equipment |                             |
| Mercedes-Benz EQA 250+ Progressive      |                             |
| Vehicle Identification number           | W1N9N0CB1PJ082386           |
| Mileage (Read)                          | 106,165 km                  |
| First registration                      | 28 Jun 2023                 |
| Number of holders                       | 1                           |
| Power / Engine displacement             | 95 kw / 0 ccm               |
| Fuel type / Cylinder                    | Electric / 0                |
| Gearbox / Number of gears               | Direct drive / 1            |
| Type of drive                           | Front drive                 |
| Type of vehicle                         | SUV                         |
| Colour / colour code                    | Digitalweiß Metallic        |
| Doors / Seats                           | 5 / 5                       |
| Upholstery type                         | Cloth / leather combination |
| Colour of upholstery                    | Black                       |



## Vehicle details

|                                                  |                                |                                |                                                            |
|--------------------------------------------------|--------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete       | <b>Next maintenance in</b>     | 287 Tag(e)                                                 |
| <b>Last service on / at</b>                      | 04/2026 at 98,551 km           |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                          | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                                | <b>Letter No.</b>              | GV706449                                                   |
| <b>Previous damage / Accident</b>                | None detectable                | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                     | <b>Lifting equipment / pit</b> | No                                                         |
| <b>Test drive</b>                                | Not performed                  | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 2222 / BEE 00009               |                                |                                                            |
| <b>Emission standard</b>                         | 2017/1151;WLTP;reine Elektrofz | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,470 kg                       | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R18 104T | Summer tyres on Light alloy | Continental  | 3mm / 3mm   |
| 2) | 235/55 R18 104T | Summer tyres on Light alloy | Continental  | 4mm / 4mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 215/60 R18 102T | Winter tyres on Light alloy | Continental  | 5mm / 5mm   |
| 2) | 215/60 R18 102T | Winter tyres on Light alloy | Continental  | 6mm / 6mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 08/2028 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- Storage compartment in center console with roller blind
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- Acoustic environmental protection
- Anti-lock braking system (ABS)
- ATTENTION ASSIST
- outdoor thermometer
- Color glass
- Third brake light in LED technology
- EASY-Pack tailgate with electric operation for opening and closing
- Velour floor mats in black
- Speed Limit Assistant
- Rear window heated
- Black fabric headliner
- Communication module (LTE) for the use of Mercedes me connect services
- Charging cable for wallbox and public charging stations, 5m, smooth (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 16 A).)
- LED High Performance Headlights
- Mercedes-Benz emergency call system
- Navigation accessories: Extended MBUX functions
- Navigation accessories: Pre-installation for remote and navigation services
- Package: Cargo space
- Package: Seating comfort
- Radio: MBUX multimedia system
- Radio accessories: Touchpad
- Remote and Charging Services Premium
- Windscreen wipers with rain sensor
- Seats: Comfort seats
- Power outlet: 12V socket in the luggage compartment
- TIREFIT with tire inflation compressor
- Immobiliser
- Decorative elements spiral look
- Adaptive Highbeam Assist
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Lane Keeping Assist
- Ambient lighting
- Rear armrest
- Electrically adjustable exterior mirrors
- Basic services
- Double cup holder
- DYNAMIC SELECT
- Chassis: Comfort chassis with lowered suspension
- Electric windows, front and rear
- Luggage net on driver and passenger seatbacks
- Transmission: Direct drive
- rear window wiper
- Climate: THERMATIC automatic climate control
- Headrests (5)
- Paint finish: Solid
- Chrome-look loading sill protector
- Charging system: Direct current charging system (DC charging)
- Charging system: Alternating current charging system (AC charging) up to 11 kW (3-phase)
- Steering wheel: Multifunction sports steering wheel in 3-spoke design in black leather
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation: Hard disk navigation
- Package: Light and Visibility Package
- Upholstery: ARTICO leatherette/fabric
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Rear view camera
- Seats: 4-way lumbar support for driver and front passenger
- Seats: Rear seat backrests foldable
- Cruise control
- High-visibility vest for drivers
- Central locking with remote control



## Extra equipment

- Airbag: Side airbags in the rear
- GUARD 360° Vehicle Protection Plus (Anti-theft alarm system - Tow-away protection with visual and audible warning in case of detected change in position - Audible alarm - Interior monitoring (triggers upon movement inside the vehicle) - Assistance with vehicle theft (theft assistance), free of charge for 3 years from activation - Emergency key deactivation, free of charge for 3 years from activation - GUARD 360° label on the front side windows - Collision detection, free of charge for 3 years from activation)
- Wheels: 45.7 cm (18") alloy wheels, 4-spoke design, in conjunction with Night Package (aerodynamically optimized, painted black and polished with 235/55 R 18 tires on 7.5 J x 18 ET 53.5 rims)
- Wheels: Complete summer wheel sets fitted at the factory
- Wheels: Winter complete wheels M+S 4-way 45.7 cm (18") light alloy wheels in 10-spoke design (black painted and gloss-turned with 215/60 R 18 on 6.5 J x 18 ET 44.5)
- Blind spot assist including exit warning function
- Exit warning function
- Paint finish: Metallic
- Package: Advanced (Fully digital instrument display, high resolution 10.25" - CENTRAL MEDIA DISPLAY 10.25" - Mirror package: interior and exterior mirrors automatically dimming, exterior mirrors electrically folding, ambient lighting of the exterior mirrors to illuminate the entry area - Parking package with reversing camera - Active Parking Assist with PARKTRONIC - Blind Spot Assist - visual and acoustic warning system)
- Package: Night (45.7 cm (18") aerodynamically optimized 5-twin-spoke alloy wheels, painted black and polished with 235/55 R 18 tires on 7.5 J x 18 ET 53.5 rims; front and rear aprons and side panels with high-gloss black inserts; high-gloss black exterior mirror housings; high-gloss black beltline trim and window line trim; black roof rails; heat-insulating dark-tinted glass from the B-pillar; black B-pillar trim)
- Heated seats for driver and front passenger
- Cargo net (This feature protects you from loose items in the luggage compartment. The cargo net is very easy to use. You can attach or remove it in just a few steps.)

## Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                                  |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |

## Value reducing factors

| No. | Component group        | Description                                                                                             |
|-----|------------------------|---------------------------------------------------------------------------------------------------------|
| 1   | Door - front left side | Door edge - Scratch(es) - Smart repair                                                                  |
| 2   | Electronic systems     | Electronic systems (Einbruch-Diebstahl Warnanlage - Alarmanlage) - Specify findings - Perform diagnosis |
| 3   | Body                   | Body - Glued / labelled - De-glue / neutralise                                                          |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.





Figure 1: Misc.



Figure 2: Misc.



Figure 3: Misc.



Figure 4: Misc.



Figure 5: Misc.



Figure 6: Misc.





Figure 7: Misc.



Figure 8: Misc.



Figure 9: Misc.



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.





Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.





Figure 19: VIN



Figure 20: Instrument cluster



Figure 21: Additional tyres



Figure 22: Mounted tyres



Figure 23: Diagonal front (left)



Figure 24: Diagonal front (right)





Figure 25: Diagonal rear (right)



Figure 26: Diagonal rear (left)



Figure 27: Interior - rear



Figure 28: Cargo area




Figure 29: Interior - front



Figure 30: Instrument panel





Figure 31: Navigation



Figure 32: Documents




Figure 33: Documents



Figure 34: Interior 360° view



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair





**Damage 1:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 2:** Electronic systems: Electronic systems (Einbruch-Diebstahl Warnanlage - Alarmanlage) - Specify findings - Perform diagnosis



**Damage 3:** Body: Body - Glued / labelled - De-glue / neutralise



**Damage 3:** Body: Body - Glued / labelled - De-glue / neutralise



**Damage 3:** Body: Body - Glued / labelled - De-glue / neutralise



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1N9N0CB1PJ082386

Hersteller / Modell: MERCEDES-BENZ MB EQA 250+ Progressive

| Datum      | KM-Stand | Beschreibung        |
|------------|----------|---------------------|
| 21.04.2026 | 98.551   | Regelwartungsdienst |
| 29.07.2025 | 73.520   | Regelwartungsdienst |
| 26.11.2024 | 49.113   | Regelwartungsdienst |
| 06.03.2024 | 23.392   | Regelwartungsdienst |