

2-FGV-209

2-FGV-209 · Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06 · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FGV-209	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ6RR124482
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	06-05-2024
Color	Blue	Odometer	61.004 ^{km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	85	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Michelin	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	6 ^{mm}	Michelin	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	5 ^{mm}	Michelin	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	6 ^{mm}	Michelin	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part

Frontdoor - Left



Damage Type

Door-edge chipped

Repair Type

Acceptable


Acceptable

Yes



Damage Part

Hood



Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Alloy - Right Front



Damage Type

Damaged

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Frontdoor - Right



Damage Type

Small scratch(es)

Repair Type

Touch-up / Polish

Acceptable

No



Damage Part

Reardoor - Right



Damage Type

Small scratch(es)

Repair Type

Touch-up / Polish

Acceptable

No




Damage Part

Bumper - Rear



Damage Type

Scratch(es)



Repair Type

Spray

Acceptable

No



Damage Part

Skirt - Left



Damage Type

Small scratch(es)

Repair Type

Polish

Acceptable

No



Damage Part

Drivers seat



Damage Type

Burned

Repair Type

Cloth Repair

Acceptable

No



Damage Part

Interior



Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No