



DS 7 CROSSBACK: 1818-MDB

Vinnumber:	VR1JCYHZUNY613553	Versionname:	7 Crossback BlueHDi DE 96kW (130CV) AT.
First Registrationdate:	27/12/2022	Fiscalpower:	PERF.LINE todoterreno 96kW 5P automática
Expertise Mileage:	56857	Power Kw:	
Bodytype:	SUV	Body colour	Light Brown
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Seats electric F L
Number keys remote	2	Seats electric F R
GPS big screen color		Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		Roof bar black
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

235/50/19/103 V				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes
Interior, Dirty, Cleaning	



Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Forfeit



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Wing trim FR, Scratch(es), Paint



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Reflector, Crack, Replace



Reflector, Crack, Replace



Tyres, No damage, Check

