

Mercedes

MERCEDES-BENZ CLA (BM 118)(02.2019->) CLA 180 D (118.310) MOTEUR 2,0 LITRE(S) - 85 KW CDI CATALYSEUR 4 PORTES

VIN: W1K1183101N287082



Description

Registration number	Registration date	Odometer
	14/02/2022	62813 km
Color	Year	Upholstery
KOSMOSBLACK - MET.	2020	-
Number of doors	Number of seats	Generation
4	5	-
CO2	Engine displacement	Gearbox type
140	1950	Manual
Engine type	Fuel Type	Number of gears
Combustion	Diesel	6
Drivetrain	Max power	
Front Wheel Drive (FWD)	85 KW	

Vehicle Equipments

Standard

beverage holder front (dual)	steering wheel (Sport) with multiple function	light alloy rims
airbag driver side/passenger side	airbag passenger side deactivatable	lap airbag front (Pelvisbag)
kneebag driver side	sidebag front	transmission 6-speed
body: 4-door	voice-command system extended functions (MBUX)	vehicle setup (online services / Apps)
USB connection in rear seat area	Electronic Stability Control (ESP)	tire pressure control system
cubic capacity 2,0 liter(s)	radio reception digital (DAB)	direct steering with variable steering assistance
side skirt vehicle colour	windshield wiper with rain sensor	diesel particulate filter
radiator grille diamond optic	Keyless Go starting system	window lifter electric front + rear
Mercedes-Benz emergency call system	communication module (LTE) preparation Mercedes me connect	engine 2,0 liter - 85 kW CDI catalyst
Light and Vision package	tire 205/55 R17 ..W	power outlet (12V outlet) front
cruise control (cruise control)	floor mats velours	vehicle monitoring (vehicle tracking system)
head airbag system (Sideguard)	antilock braking system (ABS)	driver assistance system: active brake assistant
driver assistance system: active lane-keeping assistant	driver assistance system: Multi-Sense (driving mode switch)	driver assistance system: speed limit display
multimedia system MBUX (digital multimedia system)	start/stop system	Touchpad (center console)
rear axle: four-wheel steering	central locking system with remote control	

Optional

alarm system for seat belts rear	change year with code 052 (11/2)	change year with code 802
antenna for telephone (GPS)	lumbar support seat front left and right, electrically adjustable	reversing camera
multi-functional camera	active hood	automatic air-conditioning system
Design and equipment line Progressive	Seat Comfort package	interior equipment decorative trim inserts black
roof liner cloth	seat covers/upholstery: cloth / leather look	comfort seats front
baggage net at front seatback	rear seat backrest split/folding	steering wheel (leather)
Diesel - exhaust treatment Bluetec SCR Generation 3	instrument cluster digital (virtual cockpit)	dual sun visors (sliding, extendable)
fire extinguisher	refrigerant R 1234 YF	roof liner black
Light-alloy rims	tire repair kit	exhaust system with DPF - generation 1.5
media display	R4 diesel engine OM 654	Parking package
driver assistance system: parking assistant (Active Park Assist)	mirror package	exterior mirror electrically folding
side/rear-view mirrors with automatic dimming	metallic paintwork	headlight LED High Performance
preparation car sharing	preparation digital radio	engine power reduction
seat covers/upholstery: synthetic leather Artico	seat heating front	Isofix mounts for child seat at rear seat
comfort suspension lowered (Agility Control)	driver assistance system: traffic information system Live traffic	navigation system: hard disk navigation
radiator louver top, adjustable (Airpanel)	radiator grille, active air doors	ambient lighting

Statement details



Statement date
15/07/2026

Inspection approval date
16/07/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Wing / Back Left	Scratched	Acceptable
			
002	Door / Back Right	Scratched	Acceptable
			
003	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 18 " / Surface : Diamond cut	Scratched	Repair
 			
004	Bonnet / -	Paint etching	Painting
  			
005	Wing / Back Right	Scratched	Polishing
 			

006

Bumper / Back
Painted : Yes

Scratched

Polishing



Loose Items

- ☐ Rear parcel shelf
- ☒ Tyre repair kit complete
- ☒ Document holder
- ☒ Registration certificate owner
- ☐ Toolkit
- ☐ Jack handle crank
- ☐ Slow charging cable (Type 2, Mode 2)
- ☐ Charging cable bag
- ☒ Spare Key
- ☐ Service book
- ☐ Towing hook
- ☐ Cargo net
- ☐ Remote key
- ☐ Security Kit
- ☒ Triangle
- ☐ Warranty booklet
- ☐ Hook /Hicth ball
- ☐ Card key
- ☐ Locking wheel nuts key
- ☒ Conformity certificate
- ☐ Spare wheel tyre
- ☐ Quick charging cable (Type 2, Mode 3)
- ☒ Safety vest
- ☐ Remote control
- ☐ Compressor tyre repair kit
- ☒ First aid kit
- ☒ User manual
- ☐ Jack
- ☐ Load cover
- ☐ Refill tyre repair kit
- ☒ Registration certificate
- ☐ Satellite navigation
- ☐ In-car tools
- ☐ Locking wheel nut

Main set of tyres

Front Left	BRIDGESTONE	225 / 45 / 18 / Winter	6 mm
Front Right	BRIDGESTONE	225 / 45 / 18 / Winter	6 mm
Back Left	BRIDGESTONE	225 / 45 / 18 / Winter	5 mm
Back Right	BRIDGESTONE	225 / 45 / 18 / Winter	5 mm

Comments

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation



Spare Tyre



Vin



