



SKODA SUPERB COMBI

Vinnumber:	TMBJW7NP5M7033123	Versionname:	1.4 TSI iV 160kW DSG6 Ambition
First Registrationdate:	27/11/2020	Fiscalpower:	
Expertise Mileage:	173768	Power Kw:	115
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3628
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Sun Roof electric	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar collapsible
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

215/55/17/98 V				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/55 R 17 98 V
Tyre size FR				215/55 R 17 98 V
Tyre size RL				215/55 R 17 98 V
Tyre size RR				215/55 R 17 98 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Total cost ex VAT	1380,34
Interior, Damaged, Acceptable	0,00



Bumper F, Scratch(es), Acceptable 0,00



Windscreen, Stone chip(s), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Tailgate / Boot, Dent(s), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Acceptable 0,00



Wing RR, Dent(s) and scratch(es), Acceptable

0,00



Door FR, Dent(s) and scratch(es), Repair and paint (complete)

534,95



Outer door handle FR, Scratch(es), Repair and paint (complete)

161,81



Door trim FR, Scratch(es), Repair and paint (complete)

161,81



Alloy rim FR, Scratch(es), Acceptable

0,00



Outer sill R, Chemical pollution, Repair and paint (complete)

521,77

