



Expertise

Protocol number: 46352953
Order No. / Reference: 26495188
Inspection date: 30 Jun 2026

Manufacturer: Volkswagen
VIN: WVGZZZCD6PW519223

Model: Golf Variant 2.0 TDI SCR DSG Life



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Golf Variant 2.0 TDI SCR DSG Life	
Vehicle Identification number	WVGZZZCD6PW519223
Mileage (Read)	172,748 km
First registration	24 Nov 2022
Number of holders	2
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Mondsteingrau
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	5,600 km
Last service on / at	03/2026 at 159,499 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP839538
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CNN 01408		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,060 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Summer tyres on Light alloy	Goodyear	4mm / 4mm
2)	205/55 R16 91H	Summer tyres on Light alloy	Bridgestone	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
 - Ambient lighting
 - App-Connect
 - third brake light
 - black roof rails
 - Diesel particulate filter and SCR catalyst
 - Parking assistance
 - Electronic parking brake including auto-hold function
 - Automatic headlight control, with LED daytime running lights
 - Windscreen made of laminated safety glass, heat and sound insulating
 - Speed limiter
 - Rear window heated
 - Rear spoiler in car color
 - "Climatronic" air conditioning system
 - Front headrests
 - LED taillights
 - Steering wheel: Multifunction leather steering wheel with paddle shifters
 - Non-smoking version
 - Emergency call service
 - Package: Seat Comfort Package
 - Tire pressure monitoring system (passive)
 - Wheels: Tire Mobility Set
 - Keyless start system without safe locking
 - electromechanical power steering
 - Seat belts: Three-point automatic seat belts for the outer rear seats
 - Seat covers in "Life" fabric
 - Seats: Comfort seats in the front
 - Start-stop system
 - Bumpers in body color
 - Ambient lighting with logo projection
 - Green thermal insulation glazing, sides and rear
- Airbags: Front and rear head airbags, front side airbags, center airbag
 - Exterior mirror housings and door handles in body color
 - Car2X
 - Decorative inlays "Nature Cross Brushed"
 - Digital Cockpit Pro, multicolor
 - Electronic differential lock XDS
 - Electronic stability program and electromechanical brake booster
 - Electric windows, front and rear
 - Pedestrian protection measures expanded
 - luggage compartment cover
 - Transmission: 7-speed DSG
 - Rear window wiper with intermittent function
 - ISOFIX mounting points
 - Rear headrests (3)
 - LED reading lights at the front (2) and 2 at the rear
 - LED headlights
 - Dynamic headlight range control
 - Fatigue detection
 - Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
 - Radio "Composition"
 - Wheels: Alloy wheels (4) "Norfolk" 7 J x 16
 - Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
 - Seat belts: Three-point automatic seat belt for the middle rear seat
 - Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
 - Lane keeping assistant "Lane Assist"
 - 12-volt power outlet in the luggage compartment
 - Telephone interface with inductive charging function
 - Electronic immobilizer
 - Central locking without safe locking, with remote control and 2 remote folding keys

Extra equipment

- Electrically adjustable, folding, and heated exterior mirrors.
 - Lane change assist. Side Assist, parking assist.
 - Paint finish: Special color Moonstone Grey
 - Towbar, foldable with electric release
- Package: Business Premium incl. navigation system (DSG) (6+1 speakers, App-Connect incl. App-Connect Wireless for Apple CarPlay, Android Auto, automatic distance control, adaptive cruise control (ACC) stop/go, speed limiter, emergency brake, pedestrian detection, travel assist, lane assist, emergency assist, leather multifunction steering wheel, heated, with shift paddles, multifunction camera, Discover Media navigation incl. streaming & internet (MP3, touchscreen, USB), cargo net partition, radio, heated windshield washer system, voice control, telephone interface, Comfort with inductive charging, textile floor mats, traffic sign recognition, heated front seats)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Engine	Engine - Leaking - Diagnosed and repair if necessary

Wear and tear

No.	Component group	Description
1	Body	Underbody panelling - Scratched - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	2nd wheel set	Alloy rim set - complete - Scratched - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.





Figure 27: Misc.



Figure 28: Misc.



Damage 2: Engine: Engine - Leaking - Diagnosed and repair if necessary



Wear and tear 1: Body: Underbody panelling - Scratched - No deduction



Wear and tear 2: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 2: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 5: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 5: Vehicle glazing: Windscreen - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVVZZZCD6PW519223
Hersteller / Modell: VOLKSWAGEN VW Golf Variant 2.0 TDI SCR DSG Life

Datum	KM-Stand	Beschreibung
03.03.2026	159.499	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
02.12.2025	148.263	Motoröl b. Wartung; Regelwartungsdienst
13.11.2025	144.276	AU; Wartung Sonstiges
05.09.2025	132.471	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
26.05.2025	119.750	Getriebeöl ern/prüfen
07.05.2025	117.668	Regelwartungsdienst; Wartung Sonstiges
28.01.2025	104.170	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
21.01.2025	103.088	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
23.09.2024	86.888	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Regelwartungsdienst; Systemtest/Eigendiagnose
11.07.2024	78.156	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
29.01.2024	56.818	Regelwartungsdienst
11.12.2023	51.289	Motoröl b. Wartung; Regelwartungsdienst
16.06.2023	26.498	Motoröl b. Wartung; Regelwartungsdienst