
MACADAM











BMW 2 Reeks Gran Coupe (UKL): 2CPY906

Vinnumber:	**WBA11AK0507L63516**	Versionname:	**218i Gran Coupe (F44) 1.5i 136pk/cv 4p Aut.**
First Registrationdate:	**13/10/2022**	Fiscalpower:	
Expertise Mileage:	**177482**	Power Kw:	**100**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**over 20000km of 07.2028**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/91 W**			
	Fr.L.	**Dunlop: 5 mm**	Fr.R.	**Dunlop: 5 mm**
	Re.L.	**Bridgestone: 4 mm**	Re.R.	**Bridgestone: 4 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/55 R 16 91 W**
Tyre size FR	**205/55 R 16 91 W**
Tyre size RL	**205/55 R 16 91 W**
Tyre size RR	**205/55 R 16 91 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**257**
Tyre make FR	**257**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Windscreen, Stone chip(s), Windscreen repair









Bumper moulding F, Scratch(es), Acceptable




Door FL, Dent(s), Paintless dent repair




Door RL, Dent(s) and scratch(es), Repair and paint (complete)







Alloy rim FR, Scratch(es), Acceptable




Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Sill trim R, Dent(s) and scratch(es), Repair and paint (complete)








Bodywork, Paint measurement, Acceptable

