



PEUGEOT 208: FY-822-CS

Vinnumber:	VR3UPHNEKM5803142	Versionname:	PEUGEOT 208 PureTech 100 S&S Allure Business VP [5P] bvm 6-100CH-5cv (bi-corps)
First Registrationdate:	25/03/2021	Fiscalpower:	
Expertise Mileage:	144425	Power Kw:	75
Bodytype:	Berline	Body colour:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Headlights Xenon/LED/Laser	
GPS storage		Rear parking sensors	
GPS storage	HD	Rear view camera	
Windows electric F		Seat cover lining	Lining Semi-leather
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	195/55/16/91 H			
Summer tyres:	Fr.L.	Bridgestone: 50%	Fr.R.	Bridgestone: 55%
	Re.L.	Bridgestone: 75%	Re.R.	Bridgestone: 90%
Tyre profile depth FL				4.9
Tyre profile depth FR				4.5
Tyre profile depth RL				3.5
Tyre profile depth RR				2.0
Tyre size FL				195/55 R 16 91 H
Tyre size FR				195/55 R 16 91 H
Tyre size RL				195/55 R 16 91 H
Tyre size RR				195/55 R 16 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Interior, Stain, Cleaning



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RR, Out of tolerance, Replace



Outside rear-view mirror housing L, Missing, Replace and paint



Side repeater L, Missing, Replace



Door FL, Scratch(es), Paint



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill L, Dent(s), Replace and paint



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Paint



Luggage compartment cover, Missing, Replace



Brand badge R, Incomplete, Replace



Historique Maintenance

Immatriculation: **FY-822-CS** Date de 1ère immatriculation: **25/03/2021**

Modèle: **Peugeot 208 PureTech 100 S&S Allure Business VP [5P] bvm 6-100CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
09/02/2026	138.333	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
05/02/2026	138.328	BETHUNES AUTO	LIQUIDE DE FREIN
	0		DIVERS CLIM
	0		COURROIE ACCESSOIRES RPLT
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		DISQUES PLAQUETTES AV RPLT
	0		COURROIE DISTRIBUTION RPLT
16/12/2024	117.662	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
12/12/2023	69.315	STELLANTIS &YOU FRANCE SAS	FILTRE CLIM RPLT
	0		RECYCLAGE
	0		REVISION
23/03/2023	46.872	GUEUDET ASTERIA CEOS	DISQUES PLAQUETTES AV RPLT
	0		REVISION
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE A AIR RPLT
	0		BOITIER D ALLUMAGE RPLT
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		RECYCLAGE
12/04/2022	22.764	GUEUDET ASTERIA CEOS	REVISION
	0		RECYCLAGE
	0		BALAI ESSUIE GLACE AR
	0		BALAI ESSUIE GLACE AV
	0		FILTRE CLIM RPLT