



## Volvo XC60: Z144BF

Vinnnumber:	<b>YV1UZH1VXP1380978</b>	Versionname:	<b>XC60 T6 PHEV 257kW AWD Plus-Bright automaat</b>
First Registrationdate:	<b>9/06/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>71286</b>	Power Kw:	<b>186</b>
Bodytype:		Body colour:	<b>Onyx Black metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Parking lot:	<b>496</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

## Options

Number of keys total	<b>2</b>	Lining leather
GPS		Sun Roof electric
Autom climate control		Panoramic roof
Radio multimedia		Rear parking sensors

## Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 55 / 19 / 105 / V / Aluminium	5,1 mm	Pirelli	Winter
	Right	235 / 55 / 19 / 105 / V / Aluminium	5,0 mm	Pirelli	Winter
Rear	Left	235 / 55 / 19 / 105 / V / Aluminium	4,6 mm	Pirelli	Winter
	Right	235 / 55 / 19 / 105 / V / Aluminium	4,5 mm	Pirelli	Winter


## Assistance equipment

Number of charging cables (rapid charge)	<b>1</b>
--	----------

Interior, Dirty, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)






Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper trim F, Scratch(es), Smart repair



Door FR, Dent(s) and scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)






Outside rear-view mirror housing R, Scratch(es), Replace and paint



Bumper R, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



<b>Kenteken</b>	Z144BF
<b>Merk Model</b>	Volvo XC60 T6 PHEV 257kW AWD Plus-Bright
<b>Brandstofsoort</b>	Benzine
<b>Datum deel1</b>	09-06-23

Datum reparatie	Kilometerstand	Reparatie omschrijving
24-11-25	59.038	Bougie
24-11-25	59.038	Luchtfilter
24-11-25	59.038	Onderhoudsbeurt
24-11-25	59.038	Ruitenwischerblad(en) achterzijde
24-11-25	59.038	Ruitenwischerblad(en) voorzijde
24-11-25	59.038	Volvo Check aandrijving
24-11-25	59.038	Volvo Check slijtagedelen
28-01-25	35.256	Onderhoudsbeurt
28-01-25	35.256	Ruitenwischerblad(en) voorzijde
28-01-25	35.256	Volvo Check slijtagedelen
16-01-25	34.024	Reparatie band(en)
21-06-24	10.902	Sleutel/Kaart