

Opel COMBO 1.5D 102pk L2H1 Edition+, Mar-22, 102,543 km



Memo



VIN	W0VEFYHYCMJ823900
Initial registration	04-03-2022
Initial Dutch Registration	04-03-2022
European Type Approval	e2*2007/46*0623*14
Mileage reading / hour counter reading	102,543 km 
Mileage Status:	Logical (NAP)
Automatic	No
Fuel	Diesel
Cylinders / Engine capacity	4 / 1499
Weight	1377 kg
Doors	5
Power capacity	75 kW
Emission code / Energy label	6
Wheelbase	298
Loading space	
Load capacity	978
RDW details	
Battery capacity	
Range	
Battery health	
Charging cables type	
AC/DC	
Battery purchase/rent	Unknown
Taxation	VAT (Grey number plate)
Colour	Gray
Country of registration	The Netherlands

Accessories fitted to vehicles

 Manually operated air conditioning	 Electric windows front	 Sliding door right
 Audio installation	 Lath to lath paneling / siding	 Power steering
 Bluetooth telephone connection	 Metallic paint	 Floor plate
 Central locking remote control	 Navigation	
 Cruise control	 Parking sensors rear	

Accessories fitted to vehicles (stated by offerer, conditionally)

- Airco
- Armsteun voor
- Bestuurdersairbag
- Bluetooth telefoonvoorb.
- Boordcomputer
- Buitensp. elektr. + verw.
- Cruise control
- Dimlichten aut.
- ESP
- Hill hold functie
- Lendesteunen (verstelb.)
- Multifunctioneel stuur
- Start/stop systeem
- Stoel best. hoogte verst.
- Verstelbaar stuur
- Volledig tussenschot
- Zijschuifdeur rechts



Vehicle state

MOT due date	04-03-2027	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location Owner	Wheel locks	Not present



Tyres

Rim size	16"		
Wheel	Brand	Type	Tread depth
Front wheel left	Vredestein	All Season tyre	4 mm
Front wheel right	Vredestein	All Season tyre	4 mm
Rear wheel left	Vredestein	All Season tyre	5 mm
Rear wheel right	Vredestein	All Season tyre	5 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection

Incident	Component	Observations
Unacceptable damage		
1	Koetswerk	Niet origineel
		