# VEHICLE REPORT

IT · 11/11/2026
2026-11-11 12:38

VIN: Targa: Merchant:

## VEHICLE DETAILS

| | | | |
|---|---|---|---|
| Targa | | First Registration | **2014-12-12** |
| Marca | N/A | Mileage | N/A |
| Modello e Allestimento | | Keys | N/A |
| VIN | | Owners | **2** |
| Merchant | | Seats | **5** |
| Branch | | Previous Use | **AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE** |
| KW | **103** | VAT | N/A |
| CC | **0** | Country | **IT** |
| Fuel | **GASOL** | Euro | **EURO5B** |
| GPL | **Non presente** | Cambio | **Non presente** |
| Gancio | N/A | | |

## CAR PHOTOS (58)


*Front fender left*



*Speedometer with started engine*


*Interior front.*


*Interior front*


*Interior front*


*Center console and dashboard*


*Center console and dashboard*


*Center console and dashboard*


*Center console and dashboard*


*Interior front*


*Center console and dashboard*


*Interior front*


*Interior rear*


*Interior rear*


*Interior front*


*Navigation on*


*Trunk*


*Trunk*


*Rear fender right*


*Rear*


*Left side rear*


*Front left*


*Front*


*Front left*


*Engine compartment*


*Interior front*


*Interior rear*


*Trunk*


*Trunk*


*Interior front.*


*Trunk*


*Left side rear*


*Additional photos (optional)*


*Left side front*


*Left side front*


*Rear door left*



Front door left



Front door right



Front door left



Rear fender left



Additional photos (optional)



Left side front



Trunk



Rear fender right



Center console and dashboard




Front fender left



Front fender left



Additional photos (optional)



Hood



Front fender left



Tailgate



Rear fender left



Rear fender right



Trunk



Rear fender left



Engine compartment



Engine compartment




Rear fender left