

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia			
				Policyholder				Opposite party				Opposite party company	
				Operation 2026		Claim number		Code / Agency				Date accident 27/07/2026	
				Expert code		Adjuster code		Policy number		Injured person can recover the VAT NOT ESTABLISHED			
Date assignment 27/07/2026		Date first survey 31/07/2026		Place Ascoli Piceno		C/O VAR		Repairs TO START		Photo Lien in favor of			
Ownership certificate Alphabet Italia Spa - Via Romano Guardini 24 38121 Trento (TN)										Formerly plate			
Lessee / Co-owner										Date of overhaul			
Vehicle (Brand - Model - Version) VOLKSWAGEN TIGUAN 2.0 TDI SCR 110KW Life DSG						Plate GN619DG		Vin Chassis WVGZZZ5N7PW043128		First Registration 06/03/2023			
Usage status NON CONOSCIUTO		Km 203008	Tyres % 80	Color BIANCO		Type of enamel PASTEL/DOUBLE		Consistency of damage		Type of Expert's report NOT DEFINITIVE			
Equipment													
Approval code		For commercial vehicles	Carrying Qls 0	Tare, Q 0	Wheelbase	Seats No. 0	Axles 0						
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses							
Damaged items / restoration operations						SR		LA		VE			
						Dif Time		Dif Time		Dif Time			
1 5NA845011BKNVB Windshield						S		S		S			
2 D004660M2 Window glueing kit						S		S		S			
1 5NA845051ASNVB Rear window						S		S		S			
1 5NA857537GRU External rear-view mirror cap L						S		S		S			
1 5NA949101A Fanalino lat. retrovisore est. L						S		S		S			
1 5NA823031L Front bonnet						G		G		G			
1 5NA833055L Rear door L						M		M		M			
1 5NA817101 Roof						M		G		G			
1 5NA827025M Rear hatch						M		M		M			
1 5NA821105E Front mudguard L						L		L		L			
1 5NA831055N Front door L						L		L		L			
1 5NA809843 rear mudguard L						L		G		G			
1 5NA809844 rear mudguard R						L		M		G			
1 5NA831056N Front door R						L		L		L			
1 5NA821106E Front mudguard R						L		L		L			
1 5NA833056L Rear door R						L		L		L			
1 Codice Ricambio Montante sup. L													
1 Codice Ricambio Paraurti ant.													
1 Codice Ricambio Ripr. targa ant.													
1 Codice Ricambio Paraurti post. sup. + s/r accessori													
1 Codice Ricambio Rimoz. frammenti vetrosi abitacolo + vano bagagli													
1 Codice Ricambio Igienizzazione interni													

New for old value (N)	Remarks
	Pneum. Pirelli 215/65 R17. Vhl sporco, grandinato. Spia avaria motore attiva. Portellone non apribile.