



PEUGEOT 308 3

-	
VIN	VR3FPHNSTPY682325
Première immatriculation	29/12/2023

DÉTAILS DE L'INSPECTION

Date de l'inspection	19/01/2026 10:18:38	Adresse d'inspection	
----------------------	---------------------	----------------------	--

INFORMATIONS SUR LE VÉHICULE

VIN	VR3FPHNSTPY682325	Transmission	Avant
Type de carrosserie	Berline	Nbre sièges	5
Nbre portes	5	Nombre appuis-têtes	5
Première immatriculation	29/12/2023	Couleur intérieur	Noir
Type de carburant	Essence	Couleur carrosserie	Noir
Marque	PEUGEOT	Catégorie	Vehicule particulier
Modèle	308 3	Couleur tableau de bord	Noir
Boîte de vitée	Automatique		

DOCUMENTS ET CLÉS

Carte d'entretien	Non	Manuel d'utilisation	Non
Nbre clé total	2	Certificat immatriculation (original)	Original
Nbre clés télécommandes	2	Certificat immatriculation (original)	Oui

OPTIONS

Nature de peinture	Metallisé
--------------------	-----------

DAMAGES

Interior



1 | Interior

Damage type	Stain
Repair mode	Cleaning



8 | Boot lid covering R


Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)

Exterior



2 | Door FL

Damage type	Dent(s)
Repair mode	Repair and paint (complete)




3 | Windscreen

Damage type	Stone chip(s)
Repair mode	Windscreen repair



4 | Bonnet


Damage type	Scratch(es)
Repair mode	Paint



5 | Bumper F

Damage type	Scratch(es)
Repair mode	Paint





6 | Wing RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



7 | Outer sill R

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



9 | Bumper R

Damage type	Scratch(es)
Repair mode	Paint



10 | Bumper R

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)

Commercial photos

