



### BMW i4: P175VX

Vinnnumber:	<b>WBY71AW070FN10477</b>	Versionname:	<b>i4 eDrive 40 250kW/ 83,9kWh automaat</b>
First Registrationdate:	<b>30/06/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>154515</b>	Power Kw:	<b>250</b>
Bodytype:		Body colour:	<b>Sanremo Grün metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>668</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>Yes</b>		

### Options

Number of keys total	<b>2</b>	Lining leather
GPS		Rear parking sensors
Autom climate control		Hook
Radio multimedia		


### Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 55 / 17 / 101 / V / Aluminium	5,0 mm	Hankook	Summer
	Right	225 / 55 / 17 / 101 / V / Aluminium	3,6 mm	Hankook	Summer
Rear	Left	225 / 55 / 17 / 101 / V / Aluminium	6,2 mm	Hankook	Summer
	Right	225 / 55 / 17 / 101 / V / Aluminium	5,8 mm	Hankook	Summer

### Assistance equipment

Number of charging cables (rapid charge)	<b>1</b>
--	----------

Service, Maintenance, Execute



Wing RL, Scratch(es), Repair and paint (complete)



Wing FL, Stone chip(s), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Roof pillar R, Scratch(es), Polish



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Polish



Bodywork, Paint measurement, Acceptable



<b>Kenteken</b>	P175VX
<b>Merk Model</b>	BMW i4 eDrive 40 250kW/ 83,9kWh
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	30-06-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
08-06-26	154.184	APK
17-11-25	136.063	Sleutelbatterij
01-11-25	136.063	Uitlijnen voor en achterwielen
01-11-25	136.063	Vervanging band
04-08-25	130.240	Elektromotor
04-08-25	130.240	Voertuig diagnose
02-06-25	123.263	Vervanging band
04-06-24	79.971	Onderhoudsbeurt
04-06-24	79.971	Remvloeistof
04-06-24	79.971	Sleutelbatterij
04-10-22	13.467	High Voltage batterij
03-10-22	0	Accu