


2-DMC-825

2-DMC-825 · Titanium 1.0i Ecoboost 100pk 74kw · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DMC-825	Fuel Type	Gasoline
Manufacturer	FORD	VIN	WF0JXXGAHJPE36625
Model	Fiesta	Cylinder Capacity	999 ^{cm3}
Model Versions	Titanium 1.0i Ecoboost 100pk 74kw	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	24-04-2023
Color	Grey	Odometer	70.117 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	74	Number Headrests	5

Images





Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Audio System	Leather steering wheel
Automatic air conditioning	Rear parking sensors
Bluetooth car kit	Roller cover / parcel shelf
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel - Heated
Electric rear windows	Windscreen - Heated

Condition

Condition exterior Adequate	Last Maintenance Unknown
Condition interior Adequate	Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Hankook	195 mm	60 mm	15 inch	All Season
Rear Left	3 mm	Continental	195 mm	60 mm	15 inch	All Season
Front Right	5 mm	Hankook	195 mm	60 mm	15 inch	All Season
Rear Right	3 mm	Continental	195 mm	60 mm	15 inch	All Season
Spare Tire Type	Compressor					

Damages



Damage Part
Interior



Damage Type
Scratch(es)

Notes	Repair Type	Acceptable
Pookknop	Replace	No



Damage Part
Fender – Rear Left



Damage Type
Small dent(s)

Repair Type	Acceptable
Restyle	No



Damage Part
Frontdoor – Left



Damage Type
Door-edge chipped

Repair Type	Acceptable
Acceptable	Yes



Damage Part
Wheelcover - Left Front



Damage Type
Damaged

Repair Type	Acceptable
Replace	No



Damage Part
Hood



Damage Type
Stonechipping

Repair Type	Acceptable
Acceptable	Yes



Damage Part
Fender - Front Left



Damage Type
Damaged

Repair Type	Acceptable
Spray	No



Damage Part
Wheelcover - Right Front



Damage Type
Damaged

Repair Type	Acceptable
Replace	No



Damage Part
Wheelcover - Right Rear



Damage Type
Damaged

Repair Type	Acceptable
Replace	No



Damage Part
Interior



Damage Type
Stains & dirt

Repair Type	Acceptable
Cleaning	No